

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R4424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 078922

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Canyon Largo Unit

8. FARM OR LEASE NAME

Canyon Largo Unit

9. WELL NO.

223

10. FIELD AND POOL, OR WILDCAT

Ballard Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREASec. 4, T-24-N, R-7-W  
NMPM

12. COUNTY OR PARISH

Rio Arriba

13. STATE

NM

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

PO Box 990, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

800'S, 800'E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7144'GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

8-31-73: Drilled to 2738' T.D. and logged well. Found to be dry hole.

Using drill pipe, equalize a 75 sk. (114 cu. ft.) Class "A" cement with 4% gel plug from  
Total Depth to 50' above Fruitland formation (2400').Equalize a second plug of 65 sk. (99 cu. ft.) Class "A" cement with 4% gel from 50' below  
(2160') to 50' above (1890') Ojo Alamo.At bottom of 8 5/8" surface casing (146'), spot a 25 sk. (30 cu. ft.) Class "A" neat cement  
plug.Spot 15 sk. (18 cu. ft.) Class "A" neat cement plug at surface and install Plug and Abandonment  
marker.

Clean up location and move off.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Petroleum Engineer

DATE August 31, 1973

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

SEP 4 1973