UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APP	RÓVED
OMB NO. 1	9 04-0135
Evniros: Novem	har 30 201

_	E	XDIFES. IN	<u>lovember</u>	<u>. </u>
	Lease Se	rial No.	7	

5.	Lease Serial No. JIC122	
6.	If Indian, Allotte	or Tribe Name

Do not use this form for proposals to drill or to referter an abandoned well. Use form 3160-3 (APD) for such proposals						6. If Indian, Allottee or Tribe Name JICARILLA			
					7. If Unit or CA/Agreement, Name and/or No.				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.						A ARGICCI	ment, wante and/or tvo.		
Type of Well Oil Well	her	9			8. Well Name AXI APAC)		
2. Name of Operator CONOCO INC.	Contact:	DEBORAH MA E-Mail: deborah.		noco.com	9. API Well N 30-039-2				
3a. Address P.O. BOX 2197 DU 3066 HOUSTON, TX 77252		3b. Phone No. (Ph: 281.293. Fx: 281.293.5	.1005	e)	10. Field and BLANCO	Pool, or I MESA	Exploratory VERDE/BLANCO P		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						11. County or Parish, and State			
Sec 3 T25N R4W NWSE 179	5FSL 1656FEL				RIO ARRIBA COUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE N	NATURE OF	NOTICE, RI	EPORT, OR (OTHER	. DATA		
TYPE OF SUBMISSION		was to the same of	ТҮРЕ С	OF ACTION			·		
☐ Notice of Intent	☐ Acidize	□ Deepe	n	☐ Product	tion (Start/Resu	ıme)	☐ Water Shut-Off		
■ Subsequent Report	☐ Alter Casing	☐ Fractu		☐ Reclam			☐ Well Integrity		
	☐ Casing Repair		Construction	🛚 Recomp			☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	-	and Abandon	•	rarily Abandon				
13. Describe Proposed or Completed Op	☐ Convert to Injection			☐ Water [· · · · / · · · · · · · · · · · · · · ·		
following completion of the involved testing has been completed. Final A determined that the site is ready for a This well was originally completed to the second testing the second testing the second testing testing the second testing testing the second testing	bandonment Notices shall be fi final inspection.) leted in the Blanco Mesav se zones as per the attact	iled only after all re verde and Bland	equirements, includes P.C. South	uding reclamation	on, have been con	npleted,	and the operator has		
14. I hereby certify that the foregoing is true and correct. Electronic Submission #7908 verified by the BLM Well Information System									
	For CC Committed to AFMSS fo	r processing by	Angie Medina	-Jones on 10/	12/2001 ()				
Name(Printed/Typed) DEBORA	H MARBERRY		Title SUBM	IITTING CON	NTACT				
Signature (Electronic	Submission)		Date 10/12/						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
Approved By Africa	Mleste		Titleands	and Minera	l Resources	Date	10-25/-01		
Conditions of approval, if any, are attach certify that the applicant holds legal or ea which would entitle the applicant to conditions.	quitable title to those rights in t	es not warrant or he subject lease	Office						
Title 18 U.S.C. Section 1001 and Title 4. States any false, fictitious or fraudulent	3 U.S.C. Section 1212, make it statements or representations	a crime for any per as to any matter wi	rson knowingly a thin its jurisdiction	and willfully to r	nake to any depa	rtment or	r agency of the United		

** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL **

Nestica whom well state up remin

WellName	DtTmStart	OpLast24	WelliDA
AXI APACHE O 10 (LFW 8/28/97)	5/21/2001	Csg. press. 0# tbg.press.0#, Blow well down, Latch onto long string, pull up an remove hanger. Pull up an work seal assembly loose. POOH with tbg an seal. Tally out. 95 stands, 5922'. Lay down seal assembly, RIH with 7 joints of 2 1/16" tbg. an 94 stands of 2 3/8" tbg., tag up at 5955', Bottom perf at 5922'. 33 feet of rat hole. POOH with 2 3/8" tbg. an 2 1/16" tbg. lay down 2 1/16 " tbg. Secure well SDFN	300392142900
AXI APACHE O 10 (LFW 8/28/97)	5/21/2001	Move in rig an equipment, rig up. Csg. press.30# tbg. press. 0#. Blow well down, NDWH, NUBOP, off set spool. Rig up for 1.666" tbg. Pull up an release tbg. hanger on short string. POOH with 115 joints of 1.66" tbg. Lay down on trailer. Tally out. 3709'. ND off set spool, change tools to 2 3/8" tbg. PU on long string, could not get seal assembly loose, secure well SDFN	300392142900
AXI APACHE O 10 (LFW 8/28/97)	5/22/2001	Csg. press. 100#, Blow well down, RIH with mule shoe collar, seat nipple, an 95 stands of 2 3/8" tbg., drift in. Ran packer on last stand. Set packer, NDBOP, stood back. Change out lock downs on well head. NUBOP, POOH with packer. RIH with tbg, land well at 5835'. NDBOP, NUWH. RU swab, make swab run to seat nipple. RD swab. RDPU Secure well, SDFN	300392142900
AXI APACHE O 10 (LFW 8/28/97)	5/23/2001	Move off. Well will say shut in till we get DHC order .	300392142900