V. Cementing:

Surface casing (13 3/4" x 9 5/8") - use 190 sks. of Class "B" cement with 1/4# gel-flake per sack and 3% calcium chloride (224 cu.ft. of slurry, 100% excess to circulate). WOC 12 hours. Test to 600#/30 min.

Production casing -

First stage (4 1/2" x 7 7/8") - use 143 sks. of 65/35 Class "B" Pozmix with 6% gel and 2% calcium chloride mixed with 8.3 gallons water per sack followed by 100 sks. 50/50 Class "B" Pozmix with 2% gel, 2% calcium chloride and 1/4# fine tuf-plug per cu.ft. (370 cu.ft. of slurry, 25% excess to cover the Gallup).

Second stage (4 1/2" x 8 3/4") - circulate mud for 2 hours, then cement with 361 sks. of 65/35 Class "B" Pozmix with 6% gel and 2% calcium chloride and 8.3 gallons of water per sack (585 cu.ft. of slurry, 50% excess to cover the Mesa Verde).

Third stage (4 1/2" x 8 3/4") - circulate mud for 2 hours, then cement using 243 sks. 65/35 Class "B" Pozmix with 6% gel and 2% calcium chloride mixed with 8.3 gallons water per sack (394 cu.ft. of slurry, 60% excess to cover the Ojo Alamo). Run temperature survey on top stage only at 8 hours. WOC 18 hours.

