

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	2. NAME OF OPERATOR Conoco Inc.	3. ADDRESS OF OPERATOR Po Box 460, Hobbs, Nm 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FNL + 850' FEL	5. LEASE DESIGNATION AND SERIAL NO. Contract No. 65	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	7. UNIT AGREEMENT NAME Unit Letter H	8. FARM OR LEASE NAME Jicarilla 22	9. WELL NO. 12	10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 15-25N-4W	12. COUNTY OR PARISH Rio Arriba	13. STATE Nm
14. PERMIT NO. 30-039-22744	15. ELEVATIONS (Show whether DF, RT, GR, etc.)											

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☒ Recomplete to Mesaverde	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

MIRU. NDWH. NUBOP. POOH w/ prod. tbg. Tag fill or CIBP @ 8013'. Set CIBP @ 7970'. Dump 2 sx cement on top of CIBP ($\pm 15'$). Set RBP @ 6525'. Dump 2 sx 20/40 sand on top of RBP. Load hole w/ 162 bbls. 2% KCL w/ 2 gal/1000 gals. Clay stabilizer. Test csg. to 2000# S.P. Run GR/CCL logs from 6825' - 5100' (logging tool broke). Perf. 5896' - 5800' (72 hds). Set pkr @ 5952'. Load tbg w/ 4 bbls 2% KCL. Press. test tbg + RBP to 2800 psi. Reset pkr @ 5896'. Acid. from. 5896' - 5800' w/ 36 bbls 7 1/2% HCL-NE-FE dropping 15 - 7/8" 1.3 Sg ballsealers after each 5 bbls acid. POOH w/ tbg + pkr. Frac well down csg. w/ 100,000 # 20/40 sand + 95,250 gal slickwater. Unload well up annulus with nitrogen. Swabbed. Kill well. Set RBP @ 5720'. Tested RBP + csg. Perf. 5326' - 64'. Acidize from 5322' - 5364' w/ 25 bbls 7 1/2% HCL-NE-FE dropping 15 - 7/8" 1.3 Sg ballsealers after each 5 bbls acid. Reset pkr @ 5140'. Frac w/ 40,000 # 20/40 sand + 30# gel water. Unload well w/ nitrogen. Swabbed. Set pkr @ 5177'. Squeeze Menefee perms. w/ 200' sx class "H" cement w/ 7% CF-1 fluid loss @ 1 BPM 850 psig.

18. I hereby certify that the foregoing is true and correct

SIGNED D.F. Finney TITLE Adm. Supervisor DATE 3/9/89

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE [Signature]
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 14 1989

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

BY KU

Title, 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Farmington (6) File

3/9/89

Jicarilla 22 #12 - Mesaverde Recompletion

(cont.) Press inc to 2000 psi after clearing pkr w/ cmt. Pull up 5 stds + set pkr. + press back squeeze to 1500 psi. held. Rel pkr + PooH w/tbg. GIH w/ csg scraper. Tag cement @ 5242'. Drill out to 5380'. Circ. hole. Press test to 1500 psi for 15 min. Held. CO to RBP @ 5720'. Circ. hole w/140 bbls 2% KCL w/2 gal/1000 gal Clay stabilizer. PooH w/RBP. Kill well w/55 bbls 2% KCL w/2 gal/1000 gal clay stabilizer. GIH w/prod. tbg. Land SN @ 5860'. NDBOP. NUWH. Place well on test.

