



United States Department of the Interior

IN REPLY REFER TO:

Jic. Cont. 68

162.5-1(a) (016)

BUREAU OF LAND MANAGEMENT

Caller Service 4104

Farmington, New Mexico 87499

JUL 25 1985

Texaco, Inc.
Attn: Mr. Tom Shafer
P. O. Box 810
Farmington, NM 87499


Dear Mr. Shafer:

A Getty Oil well has been looked at regarding location clean up and seeding. This well is listed on the enclosed attachment. This work should be completed by October 1, 1985.

If you have any questions relating to this well contact Jack Spears at the Farmington Bureau of Land Management Office (505) 325-4572.

Your cooperation is appreciated in resolving these matters.

Sincerely,


John Miller
Area Manager

Enclosure

WELL COMPLIANCE WORKSHEET

LEASE NO. LIC. CONT. # 68

OPERATOR GETTY OIL CO.

WELL NAME LIC. "B" # 26

Sec. 31 T. 25N R. 5W

FOOTAGE 850' FNL & 940' FEL

☐

NO WELL SIGN - (Should include well name, Sec., Twp., Rge., footage or $\frac{1}{4}$ or letter, operator, lease number.)

☐

SURFACE CONTAMINATION AND/OR SPILL

☐

CLUTTERED WITH DEBRIS AND/OR JUNK

☐

PIT NOT ADEQUATELY FENCED

☐

EXISTING FENCE WIRE SLACKING OR NOT PROPERLY BRACED

☐

NOT PROPERLY PAINTED

☐

ROAD NOT PROPERLY CONSTRUCTED

☒

OTHER THE WELL AREA SHALL BE DISCLOD AND
SEEDED WITH LIC. MIX #13, AND THE THREAD
PROTECTOR COVERS REMOVED.