

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR
Robert L. Bayless

3. ADDRESS OF OPERATOR
P.O. Box 1541, Farmington, NM 87401


4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 810' FSL & 910' FWL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☒
☒
☐
☐
☐
☐
☐
☐
☐



5. LEASE
Contract 42

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
AXI "D"

9. WELL NO.
6

10. FIELD OR WILDCAT NAME
Ballard Pic. Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 20, T24N, R4W

12. COUNTY OR PARISH
Rio Arriba

13. STATE
N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6738' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

per attached.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Kevin H. McGowan TITLE Engineer DATE May 18, 1982

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

MAY 21 1982

FARMINGTON DISTRICT

BY SM

05-12-82 Rigged up Blue Jet. Ran Gamma Ray - Collar Locator log from PBD of 2670 ft. to 2300 ft. (expected PBD was 2682 ft.). Perforated Pictured Cliffs interval as follows:

2544-2563	19 ft.	10 holes
2569-2583	14 ft.	7 holes
2598-2609	11 ft.	6 holes

total 44 ft., 23 holes (1 shot every 2 ft.)

Rigged up The Western Co. Broke down perforations at 3500 psi. Established rate into perfs of 6.1 BPM @ 2100 psi. ISIP=1000 psi. Acidized Pictured Cliffs interval with 250 gallons of 7½% HCL acid and 33 RCN ball sealers, 5.4 BPM @ 1700 psi. ISIP=1000 psi. Had some ball action; did not balloff. Rigged up Blue Jet and ran junk basket to retrieve balls. Fracture stimulated Pictured Cliffs interval with 42,300 gallons 70 quality foam and 37,340 lbs. 10/20 mesh sand as follows:

10,000 gal. foam pad	20 BPM @ 2800 psi
5,000 gal. 1 ppg 10/20 sand	20 BPM @ 2700 psi
4,620 gal. 2 ppg 10/20 sand	20 BPM @ 2700 psi (well started screening out, sand concentration was lowered)
8,400 gal. ¾ ppg 10/20 sand	20 BPM @ 3250 psi
8,610 gal. 1 ppg 10/20 sand	20 BPM @ 2900 psi
5,460 gal. 1½ ppg 10/20 sand	20 BPM @ 2950 psi
210 gal. foam flush sand	20 BPM @ 4000 psi (well totally sanded off)

ISIP = 4000 psi
5 min.=3100 psi
10 min.=2800 psi
15 min.=2700 psi

(shut-in pressures)

Average foam rate 20 BPM; average pressure 2900 psi; maximum pressure 4000 psi; minimum pressure 2650 psi; average nitrogen rate was 6000 scf/min. Total nitrogen pumped 303,640 scf. Load to recover 339 bbls. Let fracture heal 2 hrs. Opened well to the atmosphere. Well flowing to cleanup for AOF.