

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

Form Approved  
Budget Bureau No. 42-51424

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE J-37-B	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME	
9. WELL NO. #2 Martin-Blackford	
10. FIELD OR WILDCAT NAME Ballard P.C.	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NE NW 13 T24N R5W	
12. COUNTY OR PARISH Rio Arriba	13. STATE N.M.
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) Gr. 6613'	

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR  
W. B. Martin Sr. and W. B. Martin Jr.

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 790' FWL and 1850' FNL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>

(other) Permission to Plug and Abandon

**RECEIVED**  
(NOTE: Report results of multiple completion or zone change on Form 9-330.)  
AUG 25 1982

17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Completed Operations: Drill to 2560' T.D. with Rotary Tools using Low water loss mud. Pictured Cliff formation dry, no shows.

Proposed Operations: Plug and Abandon. Plugging Program as Follows  
Plug with 100' cement or 25 sacks which ever is greater.

Bottom Plug	From	To
	2509'	2409'
	2219'	2119'
	1634'	1534'
	147'	47'

Cement dry hole marker at surface casing.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED W.B. Martin Jr. TITLE Operator DATE August 23, 1982

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

**ACCEPTED FOR RECORD**

\*See Instructions on Reverse Side

SEP 03 1982

**NMOCC**

FARMING  
BY Sm