Form 3160-5 UNITED STATES (June 1990) DEPARTMENT OF THE INTERIOR FORM APPROVED Budget Bureau No. 1004-0135 BUREAU OF LAND MANAGEMENT Expires: March 31, 1993 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS ALEBUTEROUS. IN. NM13771 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allonee or Tribe Name Use "APPLICATION FOR PERMIT-" for such proposals SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of Well X Oil Other 2. Some of Operator 8. Well Name and No. BUS RX, INC. BUS RX, INC. 1 Andress and Telephone No. 9. API Well No. P O Box 35938, Tucson, AZ. 85740 30-039-23046 Location of Well (Footige, Sec., T., R., M., or Survey Description) (520) 623-2211 10. Field and Pool, or Exploratory Area East Puerto Chiquito 475' FNL, 990' FEL Sec 16, T25N, R21E 11. County or Parish, State RIO ARRIBA, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Change of Plans Subsequent Report Recompletion New Construction Plugging Back Final Abandunment North Non-Routine Fracturing Casing Repair Water Shut-Off Aliering Casing Conversion to Injection Dispose Water Describe Proposed or Completed Operations (Clearly state all perment details, and give portinent dates, including estimated date of starting any proposed work. If well is directionally drilled. Rig down Triple "P: Well Service. Set Up surface Equipment & 30 bbls tanks. 10/3/95 Rigged up Triple "P" Well Service. Pulled production. 10/9/95 10/10/95 Ran in hole with Plug & packer & tested 7" casing. 10/11/95 Pulled 4½" liner out of hole. Changed out 2-3/8" tubing with 2-7/8" tubing. 10/12/95 10/13/95 Circulated cave in material out with Oil & 6" Bit. 10/14/95 Clean hole. Ran in hole with inflatable packer and set it @ 2577' with 25' of 2-3/8" tail pipe. Returned production rods & 2" X 14 X 12 rod pump into hole. Rig down Triple "P" Well Service. 10/16/95 10/17/95 Well sanded in rod pump. Production 8 bbls. Rigged up Triple "P" Well Service - Pulled Production Rods. Shut in for night. 10/19/95 Taged fluid level @ 400' from surface. Swabed fluid level down to seating nipple 10/20/95 WIH with new 2 X 12X12 rod pump & put on production pump 5 bbls. Broke suction. 10/21/95 Fluid level in hole may be restricked by bottom pump up plug for Baker Inflatable packer. thereby certify that the foregoing is true and correct President Title 10/23/95 (This space for Poderal or State office use) Approved by Koles. Condinons of approval, if any: Chief, Lands and Mineral Resources 2 8 1995