

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE  
(Other instructions on reverse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-40540

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS **RECEIVED**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☐ OTHER ☐

OCT 28 1985

2. NAME OF OPERATOR

Amoco Production Co.

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, N M 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1650' FNL X 990' FWL

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Amoco Fed. Oso Canyon

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat Gallup/Wildcat Dako

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

SW/NW Sec 24, T24N, R2W

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, CR, etc.)

7445' GR

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Supplemental

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set cast iron bridge plug at 7070' on 7-17-84 to isolate the Dakota formation. Pressure tested bridge plug at 3850 psi.

Cement Reduc.  
2898' / 30' of mudlogs  
CIBP at 7070

**RECEIVED**

OCT 31 1985

OIL CON. DIV.  
DIST. 3

I hereby certify that the foregoing is true and correct

SIGNED B. S. Shaw

TITLE Adm. Supervisor

DATE 10-21-85

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE OCT 30 1985

FARMINGTON RESOURCE AREA

BY Sm

\*See Instructions on Reverse Side

NMOCC