

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals


SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
CHAPARRAL ENERGY, INC.

3. Address and Telephone No.
701 CEDAR LAKE BLVD., OKLAHOMA CITY, OK 73114 (405) 478-8770

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SE/NW of Sec. 11-24N-2W
1660' FNL & 1840' FWL



5. Lease Designation and Serial No.

NMNM 40635

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Oso Canyon Federal "B" #1

9. API Well No.

30-039-23521-S1

10. Field and Pool, or Exploratory Area

Gavilan Mancos Ext-U

11. County or Parish, State

Rio Arriba, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input checked="" type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRUCU, POOH w/rods and pump, lay rods down in singles, dope threads and boxes, prepare to move to storage, shop pump.
2. Release TA, ND wellhead, NUBOP.
3. RU to scan tbg while pooh. Set 5 1/2" CIBP at 6700', cap with cement. Load hole with 2% KCL. Pressure test to 2000 psi.
4. Perf Pictured Cliff at 3348' - 3354' and 3357' - 3364' with 4" casing gun 3 spf. RD WL.
5. TIH w/tbg and pkr, set pkr at ~ 3300', swab down to SN.
6. MIRU pump trucks, breakdown perfs with 500 gals, 7 1/2" HCL and ball sealers.
7. Swab, test, evaluate.
8. Release pkr and POOH with tbg, prepare to frac down casing.
9. Frac with nitrofluid and ~ 60,000 lbs of sand, flush with N2.
10. Flow back until well dies.
11. TIH w/tbg, swab and flow back to clean up, test and evaluate, put on production.

14. I hereby certify that the foregoing is true and correct.

Signed Trish Hambricht

TRISH HAMBRIGHT
Title ENGINEERING TECH

Date 10/02/01

(This space for Federal or State office use)

/s/ Brian W. Davis

Title Lands and Mineral Resources

Date OCT 25 2001

Approved by
Conditions of approval, if any:

Need plat

RECEIVED
OCT 11 AM
2001
Oso Canyon

Need plat
(C-102)
for S. Blanco
Pictured Cliffs
72739

IN REPLY REFER TO
3162.3-1 (017)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
Albuquerque Field Office
435 Montano N.E.
Albuquerque, New Mexico 87107

Company Chaparral Energy, Inc.

Well No. Oso Canyon Federal B No. 1

Location 1660' FNL & 1840' FWL Sec.11, T24N, R2W, NMPM

Lease No. NMNM-40635

Government Contacts:

Bureau of Land Management , Albuquerque Field Office Office 505.761.8700
Manager: Steve Anderson, Assistant Field Manager 505.761.8982
Petroleum Engineer: Brian W. Davis 505.761.8756, Home 505.323-8698,
Pager 505.381.0346, Cell 505.249.7922,
Petroleum Engineering Technician: Al Yepa 505.252.6981 and 505.289.3748
BLM Geology / Environmental Contact: Patricia M. Hester 505.761.8786

GENERAL REQUIREMENTS
FOR
OIL AND GAS OPERATIONS ON FEDERAL AND INDIAN LEASES

1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
2. For wells on Indian leases, Bryce Hammond with the Jicarilla Nation Tribal Oil and Gas Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-1823, x-31 office, (505) 320-9741 cell. Office hours are 7:45 a.m. to 4:30 p.m.
3. Blowout prevention equipment is required.
4. The sundry is approved with the following change:

Place 19 sxs over CIBP for to ABD zone permanently.