

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 23032	
2. NAME OF OPERATOR JEROME P. McHUGH		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P O Box 809, Farmington, NM 87499		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL - 1850' FEL		8. FARM OR LEASE NAME New Horizon	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 7253' GL; 7265' KB		10. FIELD AND POOL, OR WILDCAT *Gavilan Mancos	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2, T24N, R2W, NMPM	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE NM	

RECEIVED

SEP 23 1985

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Not Complete
*Plan to temporarily abandon the Dakota formation, since it does not appear to be economically feasible to produce at this time. The Dakota formation has not been perforated and was properly cemented during the primary cement job.

Plan to complete only the Gavilan Mancos formation at this time.

RECEIVED
SEP 25 1985
OIL CON
LIST

18. I hereby certify that the foregoing is true and correct

SIGNED

James S. Hazen

TITLE Field Supt.

DATE 9/19/85

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE SEP 24 1985

John Miller

M. MILLENBACH

AREA MANAGER

*See Instructions on Reverse Side

NMOCC