Form 3160-5 (August 1999)

## UNITED STATES

FORM APPROVED

Obur	NO. 1004	-UI.	55
Expires:	November	30,	2000

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			Expires: November 30, 2000  5. Lease Serial No. JIC 148  6. If Indian, Allottee or Tribe Name				
						, , , , , , , , , , , , , , , , , , ,	
			SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA
1. Type of Well  ☐ Oil Well ☑ Gas Well ☐ Other			8. Well Name an JICARILLA (	nd No. CONTRACT 148 17Y	<u></u>		
Name of Operator     BP AMERICA PRODUCTION COMPANY     Contact: CHERRY HLAVA     E-Mail: hlavacl@bp.com			9. API Well No. 30-039-237				
3a. Address P.O. BOX 3092 HOUSTON, TX 77253  3b. Phone Ph: 281 Fx: 281.				)	10. Field and Pool, or Exploratory LINDRITH GALLUP DAKOTA, WEST		3T
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description	i)			11. County or Parish, and State		
Sec 15 T25N R5W NWSE 99	OFSL 790FEL				RIO ARRIE	BA COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NA	ATURE OF 1	NOTICE, RE	PORT, OR O	THER DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
	☐ Acidize	☐ Deepen		☐ Producti	on (Start/Resun	ne)	
Notice of Intent     ■	☐ Alter Casing	☐ Fracture	Treat	☐ Reclama	tion	☐ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New Co	nstruction	☐ Recomp	lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug an	d Abandon		arily Abandon		
	☐ Convert to Injection	☐ Plug Ba	ck	□ Water D	isposal		
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  On 6/14/01 Amoco sent update to P&A to advise that the plug and abandonment operations had not been initiated and it was our intention to commence P&A operations within the 3rd or 4th quarter of 2001. Place withdraw our NoT +o PlA  BP America respectfully requests to T&A the subject well in order to hold for rehabilitation of the DK or for a future saltwater disposal well. Please see the attached procedure.							
14. I hereby certify that the foregoing i	Electronic Submission For BP AMERICA P	RODUCTION GON	MPANY, sent	to the Rio Pu	e( <b>co</b> .	;	
Namc (Printed/Typed) CHERRY	HLAVA Chorry 9	Hava T	itle AUTH	ORIZED REP	PRESENTATIV	/E	
Signature (Electronic	Submission)		ate 05/07/		<del></del>		
	THIS SPACE F	OR FEDERAL	OR STATE	OFFICE U	SE	<u> </u>	
/s/ Patricis	M. Hoster	Li 	nds and N	/ineral Res	ources	Date MAY 1 4 2002	
Conditions of approval, if any, are attach certify that the applicant holds legal or owhich would entitle the applicant to conditions.	quitable title to those rights in t	es not warrant or he subject lease	Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## San Juan Basin Well Work Procedure

Jicarilla Contract 148-43

Well Name: Version:

Date: Budget: Repair Type:	<b>3/25/2002</b> DRA <b>TXA</b>				
Objectives:					
•	bore and perform mechanical ir on.	ntegrit	y test. Hold for reh	nabilitation of th	ne DK or future SWD
Pertinent Info Location: County: State: Lease:	rmation: Sec 15 T25N R5W Rio Arriba New Mexico			Horizon: API #: Engr: Phone:	Basin Dakota 30-039-23713 Allen Kutch (281)366-7955
Formation To Nacimento: Ojo Alamo: Kirtland Shale Fruitland: Pictured Cliffs Lewis Shale: Chacra: Cliff House:			Menefee: Point Lookout: Mancos Shale: Gallup: Graneros: Dakota: Morrison:	6444 7452	
Bradenhead Test Date:	Test Information: Tubing:		Casing:	вн:	
Time BH	CSG	INT	CSG		
5 min 10 min 15 min					
Comments:					

## Temporary abandonment procedure

- 1. Contact Federal and State agencies prior to starting work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM Brian Davis 505-761-8756).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. POOH and LD pump x rods. ND wellhead. NU BOP's.
- 6. Unset TAC at 7093' and POOH with 2-3/8" tbg, visually inspecting.
- 7. Make bit x scraper run.
- 8. TIH with CIBP on tbg. Set CIBP at 7275'.
- 9. Load csg with inhibited lease water.
- 10. Attach chart recorder. Test casing to 550 psi for 30 minutes. Fax copy of chart to 281-366-0700, attention Allen Kutch.
- 11. RIH with 2-3/8" tbg. ND BOP, NU WH.
- 12. RDMO SU.

Jicarilla Contract 148-43 - Proposed TXA Configuration 3-25-2002
Rio Arriba County, NM ATK
Unit P Section 15 T25N - R5W
Run 65

