Form 3160-5 (August 1999)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

Lease Serial No. JIC CONTRACT 148

	JIC	C	ONTE	₹A(	CT	14	18	
_				_		_		
,						~	٠.	

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals

abandoned well. Use form 3160-3 (A	JIC APACHE	
SUBMIT IN TRIPLICATE - Other instr	Y. If Unit or CA/Agreement, Name and/or No.	
i. Type of Well ☐ Oil Well ☑ Gas Well ☐ Other		8. Well Name and No. JIC APACHE 148 37
2. Name of Operator Contact: AMOCO PRODUCTION COMPANY	CHERRY HLAVA E-Mail: hlavacl@bq.com	9. API Well No. 30-039-23786
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code). Ph: 281.366.4081 Fx: 281.366.0700	10. Field and Pool, or Exploratory W. LINDRITH GALLUP-DAKOTA
4. Location of Well (Footage, Sec., T., R., M., or Survey Description	11. County or Parish, and State	
Sec 13 T25N R05W NENW 990FNL 1660FWL		RIO ARRIBA COUNTY, NM

12.	CHECK APPROPRIATE BOX(ES	TO INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
-----	--------------------------	------------------------------	-------------------------

TYPE OF SUBMISSION	TYPE OF ACTION				
■ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
Nonce of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon		
	☐ Convert to Injection	Plug Back	☐ Water Disposal		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

On June 28, 2000 Amoco Production Company requested permission to plug & abandon this well and was granted permission to P&A on 7/19/00. It remains our intent to P&A this well but we respectfully request an extention to the 4th quarter of 2002.

weil	must be in confliance w.	In Rule 201 B Befele 6-	01-2002		
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #8857 verified by the BLM Well Information System  For AMOCO PRODUCTION COMPANY, sent to the Rio Puerco  Committed to AFMSS for processing by Angie Medina-Jones on 10/13/2001 ()					
Name (Printed/T	Typed) CHERRY HLAVA	Title AUTHORIZED REPRESENTATIVE			
Signature	(Electronic Submission)	Date 11/12/2001			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By	friem my Hoster	द्वितृतिक and Mineral Resources Date // -	16-01		
certify that the applica	al, if any, are attached. Approval of this notice does not warrant of ant holds legal or equitable title to those rights in the subject lease he applicant to conduct operations thereon	Office			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## **BLM CONDITIONS OF APPROVAL**

The following surface rehabilitation Conditions of Approval must be complied with as applicable, before this well can be approved for final abandonment (see 43 CFR 3162.3-4). Surface rehabilitation work shall be completed within one year of the actual plugging date. Notification for completion of this work should be submitted with a Sundry Notice. Questions? Call Pat Hester at (505) 761-8786.

- 1. All fences, production equipment, purchaser's equipment, concrete slabs, deadman (anchors), flowlines, risers, debris and trash must be removed from the location. Non-retrieved flowlines and pipelines will be abandoned in accordance with State Rule 714. Information supporting the non-retrieval will be included in the subsequent report or final abandonment Sundry Notice.
- 2. Production pits will be closed according to the Unlined Surface Impoundment Closure Guidelines, as approved in the Environmental Assessment of December 1993. Any oil stained soils can be remediated on-site according to these guidelines or disposed of in a an approved facility.
- 3. The well pad will be shaped to the natural terrain and left as rough as possible. All compacted areas and areas devoid of vegetation shall be ripped to a minimum of 12" in depth before reseeding.
- 4. Access roads will be shaped to conform to the natural terrain and left as rough as possible to deter vehicle travel. Access will be ripped to a minimum of 12" in depth, water barred and reseeded. All erosion problems created by the development must be corrected prior to acceptance of release. Water bars should be spaced as shown below along the fall line of the slope:

% Slope	Spacing Interval
Less than 20%	200'
2 to 5 %	150'
6 to 9 %	100'
10 to 15 %	50'
Greater than 15%	30'

- 5. All disturbed areas will be seeded with the prescribed certified seed mix (reseeding may be required). Seed mix must be certified weed free to avoid the introduction of noxious weeds. Refer to the original APD for seed mix.
  - 6. Notify Surface Managing Agency seven (7) days prior to seeding so that they may be present to witness.
- 7. The period of liability under the bond of record will not be terminated until the well is inspected and the surface rehabilitation approved.

Other Surface Managing Agencies (SMA's) may vary slightly in their restoration requirements. It is your responsibility, as the operator, to obtain surface restoration requirements from other SMA's. We need to be provided with a copy of these requirements. Any problems concerning stipulations received from other SMA's should be brought to us. On private land, a letter from the fee owner stating that the surface restoration is satisfactory will be provided to the office. Questions? Call Pat Hester at (505) 761-8786.

IN REPLY REFER TO 3162.3-1 (017)

#### UNITED STATES DEPARTMENT OF THE INTERIOR

### BUREAU OF LAND MANAGEMENT Albuquerque Field Office 435 Montano N.E. Albuquerque, New Mexico 87107

Company Amoco Production Company

Well No. Jicarilla Contract 148 # 37

Location 990' FNL & 1660' FWL Sec. 13, T25N, R5W, NMPM

Lease No. Jicarilla Contract 148\_\_

Government Contacts:

Bureau of Land Management, Albuquerque Field Office Office 505.761.8700

Manager:

Steve Anderson, Assistant Field Manager 505.761.8982

Petroleum Engineer:

Brian W. Davis 505.761.8756, Home 505.323-8698,

Pager 505.381.0346, Cell 505.249.7922,

Petroleum Engineering Technician: Bryce Hammon, Office 505.759.1823, x-31, Cell 505.320.9741

BLM Geology / Environmental Contact:

Patricia M. Hester 505.761.8786

# GENERAL REQUIREMENTS FOR OIL AND GAS OPERATIONS FEDERAL & INDIAN LEASES

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."
- 2. For wells on Indian leases, Bryce Hammond with the Jicarilla Nation Tribal Oil and Gas Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-1823, x-31 office, (505) 320-9741 cell. Office hours are 7:45 a.m. to 4:30 p.m.
- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made: Addition of a Nacimentor plug from 1690 to 1790 was a COA of the previous sundry dated 6/28/01.