• •	UNITED STATES RTME. OF THE INTERI		5. LEASE DESIGNATION AND SERIAL NO. NM 23043
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN ALLOTTER OR TRIBE NAME
OIL CAS WELL OTHER  2. NAME OF OPERATOR			7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME
Schalk Development Company			Schalk-Gavilan
3. ADDRESS OF OPERATOR			9. WELL NO.
P.O. Box 25825, Albuquerque, NM 87125			1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  *At surface			West Lindrith-Gallup/Dakota
NW/4 NE/4 Section 34			11. SBC., T., E., M., OR BLK. AND SURVEY OR ARMA
RECEIVE L	15. ELEVATIONS (Show whether DF 7,289' GL	, RT, GR, etc.)	Sec. 34; T25N; R3W 12. COUNTY OR PARISH 13. STATE Rio Arriba NM
<u> </u>			
16. Check BUREAU OF LAND MANAGEMEN	k Appropriate Box To Indicate N	lature of Notice, Report, or	Other Data
FARMINGTON RESOURCE AREA	INTENTION TO:	SUBSI	QUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
PRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	shooting or acidizing change hold	and casing size
change hole and casing size (Note: Report results			ts of multiple completion on Well
17. DESCRIBE PROPOSED OR COMPLETE	D OPERATIONS (Clearly state all pertinen	t details, and give pertinent date	pletion Beport and Log form.) es, including estimated date of starting any ical depths for all markers and zones perti-
We request perm 300' to 8,500' to 5 1/2", 17# of cement being		ng from 4 1/2", 11.6	5#, J55 ST&C casing
S1	tage 1 - 498 cu. ft. tate 2 - 346 cu. ft. tage 3 - 844 cu. ft.		
			DEC 1 0 1985
i		O	IL CON. DIV. \ DIST. 3

\*See Instructions on Reverse Side NMOCC

(This space for Federal or State office use)

MILLENBACH AREA MANAGER