6810-7010' - 1 shot per 2' 7160-7260' - 1 shot per 2' 2. Breakdown perfs. Swab test well. 3. Results of swab test to determine if refrac is ne	cessary.
7160-7260' - 1 shot per 2' 2. Breakdown perfs. Swab test well.	
6810-7010' - 1 shot per 2' 7160-7260' - 1 shot per 2'	
1. Perforate additional holes as follows:	
(Norm: Report results	of multiple completion on Well tion Report and Log form.)
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL MULTIPLE COMPLETE ABANDON* SHOOTING OR ACIDIZING CHANGE PLANS (Other) Reperf & F	ALTERING CABING ABANDONMENT* Refrac Galling
TEST WATER BHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	BNT REPORT OF: REPAIRING WELL
16. Check Appropriate Box To Indicate Nature of Notice, Report, or C	
7320' GR	Rio Arriba NM
2900' FNL & 1650 FEL 14. PERNIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	Sec. 1-T25N-R3W
	O jito-Gallup-Dakota 11. smc., r., s., m., or slk. amb survey or arma
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
8. ADDRESS OF OPERATOR P. O. Box 1258, Farmington, NM 87499	9. WHILL NO.
2. NAME OF OPERATOR Curtis J. Little Oil & Gas	8. FARM OR LEASE NAME Hurt Federal
OIL X GAS OTHER	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	
	SF-080539 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
BUREAU OF LAND MANAGEMENT	

*See Instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.