	.055/N; 824/ @w			w	Sx. Pr Prod. Stim.	@	\	~	Sx. T		_@ 	Ţ Gas
· · · · · · · · · · · · · · · · · · ·	BO/D				Grav.							N S
	MCF/D After	Т -		Well Log	Days GOR	TEST DAT						
	TOPS	NITD C-103	X	Plat		Schd.	PC	Q	PW	PD	D	Ref.No
Ojo Alamo		C-103		Electric Lo	X							
Kirtland 		C-104	1	C-122	-							
Pictured Cliffs		Ditr	1	Dfo								
Chacra		Datr		Dac								
Cliff House												
Menefee		-										
Point Lookout		1										<u> </u>
Mancos		┦						<u> </u>				
Gallup		1						ļ	ļ	<u> </u>	↓	
Greenhorn							<u> </u>	<u> </u>		ļ <u>.</u>	_	-
Dakota							 	<u> </u>		 	-	
Entrada					NSL-267A Acresw/79.32	2						

Goff 30 #5R

E-30-24N-06W

BANNON ENERGY, INC.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington Resource Area 1235 Laplata Highway Farmington, New Mexico 87401



IN REPLY REFER TO-SF-078562 (WC) 3162.3-1.0 (019)

MAR. 9 1992

Bannon Energy, Inc c/o Daggett and Chenault Attention: Mr. Bob Larson 3539 East 30th, Suite 7B Farmington, NM 87401

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 5R Goff 30, Sec. 30, T. 24 N, R. 6 W, Rio Arriba County, New Mexico, lease SF-078562. As discussed with Bob Larson, a representative of your company on February 21, 1992, the subject APD is rescinded and returned due to drilling not being commenced within the approved period of time.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Is John L. Kener

John L. Keller Chief, Branch of Mineral Resources

1 Enclosure

cc:
New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410

ABANDONED LOCATION

