FORM APPROVED **UNITED STATES** 1-5 Budget Burgau No. 1004-0135 Fort DEPARTMENT OF THE INTERIOR (Jun Expires: March 31, 1993 BUREAU OF LAND MANAGEMENT 5. Lease Designation and Serial No SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Nam and use this form for proposals to drill or to deepen or reentry to a different reservoir. Jicarilla Apa ∈ e Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Desig account SUBMIT IN TRIPLICATE 1. Type of Well 8 Well Name and No. Apache Eim okidge (214)696-8090 Resources, 9. API Well No. 30-039-Greenville Ave., Suite 1305, Dallas, Tx. 75206 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin Dakota 11. County or Parish, State Surface: NWNE 18-24a-5w Rio Arriba, NM BHL: Same CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Abandonment Notice of Intent **New Construction** Recompletion Non-Routine Fracturing Plugging Back Subsequent Report

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is direction give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Altering Casing

History

Water Shut-Off Conversion to Injection

Dispose Water
(Note: Report results of multiple completion or Recompletion Report and

illed

Only change from APD in surface casing - 235' run instead of planned 200'

Well was spudded approximately 1845 pm September 30, 1995.

Final Abandonment Notice

Surface casing was landed and plug down at 0130 Oct. 1. At 0830 Oct. 1 a few intermittent gas bubbles were noted in mud in the cellar. Appeared to be coming up annulus. Doug Endsley called OCD and Farmington BLM (Albq. BLM unavailable). After WOC 10 hours, pressured up casing, drilled out cement and into 10' of new formation. Pressured up formation. No circulation out of the annulus. Drilled ahead for one hour - no more bubbles. Pumped out the cellar, found TOC within 2' of grade. Filled cellar with water - no more bubbles.

	cc: BIA, BLM (& OCD),	Elm Ridge (D&F),
14. I hereby certify that the loregoing is true and correct Signed	Consultant (505) 466-8120	10-20 j
(This space for Federal or State office use) Approved by Local Conditions of approval, if any:	Chief, Lands and Mineral Resources	Date NOV 3 0 1995