Form 9-381 (Feb. 1951)	а



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Offic	Santa Fe
Lease No.	078915
	indrith Unit
Onit	Y_550. 713

NOTICE OF INTENTIO	N TO DRILL		SUBSEQUENT REPOR	T OF WATER SHUT-OFF
	N TO CHANGE PLANS	1 1	SUBSEQUENT REPOR	T OF SHOOTING OR ACIDIZING
NOTICE OF INTENTIO	N TO TEST WATER SHUT-OF	F	SUBSEQUENT REPOR	T OF ALTERING CASING.
OTICE OF INTENTIO	N TO RE-DRILL OR REPAIR	WELL	SUBSEQUENT REPOR	T OF RE-DRILLING OF REPAIR
OTICE OF INTENTIO	N TO SHOOT OR ACIDIZE		SUBSEQUENT REPOR	
NOTICE OF INTENTIO	ON TO PULL OR ALTER CASIN	۱G	SUPPLEMENTARY WE	LL HISTORY JUL 22 1957
NOTICE OF INTENTIO	ON TO ABANDON WELL			U. S. GEULUWA
	(INDICATE ABOVE BY	Y CHECK MARK NATU	RE OF REPORT, NOTI	CE, OR OF AR DATE
				July 17 19
				, 17
		(1)	V)	
ell No. 17	is located 90	ft. from	line and	$\frac{C}{W}$ ft. from $\frac{E}{W}$ line of sec. 2
IN Sec.	. 22 2h	. E	e N	.M.P.M.
(½ Sec. and Se		wp.) (Rang	ge)	(Meridian)
Wilden		Rio Arrib	e.	New Mexico
(Field)		(County or Sub	division)	(State or Territory)
	the derrick floor ab	DETAILS	OF WORK	f proposed casings; indicate mudding jobs, ce
		DETAILS	OF WORK	f proposed casings; indicate mudding jobs, ce work)
3-21-5 Ran 62 3260' 1 follow Hald 1		DETAILS sands; show sizes, we coints, and all other 260'. 15.50*, J-5 gular cement regular cement	OF WORK eights, and lengths of important proposed 5 casing (3 t, 50 sacks	250') set at Fosmix, 4% gel
3-21-5 Ran 62 3260' follow Hald 1 Top of	7. Total Bapth 3 2 joints 5-1/2", with 50 sacks read by 50 sacks 1 000 for 30 minutes	DETAILS sands; show sizes, wo coints, and all other 260'. 15.50', J-5 cular censury regular censury regular censury regular censury	OF WORK eights, and lengths of important proposed 5 casing (36 t, 50 sacks at.	250') set at Fosmix, 4% gel
3-21-5 Ran 62 3260' follow Held 1 Top of	7. Total Bapth 3 2 joints 5-1/2", with 50 sacks read by 5	DETAILS sands; show sizes, wo coints, and all other 260'. 15.50', J-5 cular censury regular censury regular censury regular censury	OF WORK eights, and lengths of important proposed 5 casing (36 t, 50 sacks at.	Posmix, 4% gel
3-21-5 Ran 62 3260' follow Hald 1 Top of	rected depths to objective a fing p 7. Total Bapth 3 2 joints 5-1/2**, with 50 sacks rected by 50 sacks rected by 50 sacks rected by 50 sacks rected by temperature by temperature this plan of work must rected to the sacks rected by temperature by temperature by temperature rected to the sacks rected by temperature rected by temperature rected to the sacks recte	DETAILS sands; show sizes, wo coints, and all other 260'. 15.50', J-5 cular censury regular censury regular censury regular censury	OF WORK eights, and lengths of important proposed 5 casing (36 t, 50 sacks at.	Posmix, 4% gel
3-21-5 Ran 62 3260' follow Held 1 Top of	7. Total Bapth 3 2 joints 5-1/2", with 50 sacks read by 5	DETAILS sands; show sizes, wo coints, and all other 260'. 15.50', J-5 squiar censure gular censure surv eive approval in write Gas Co.	OF WORK eights, and lengths of important proposed 5 casing (30 t, 50 sacks at. ey at 2310 ting by the Geological	Posmix, 4% gel