

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR *ince Abraham*  
(Jay J. Harris)(filed by E.P.E.X.)

3. ADDRESS OF OPERATOR  
801 Ridgecrest Drive, Albuquerque, N. M.

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

*Brandon* ☒

(other)

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☒

RECEIVED

NOV 03 1983

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

5. LEASE *Contract 13?*  
Jicarilla Apache *Contract 12*

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla *Chick*

9. WELL NO.

No: 2

10. FIELD OR WILDCAT NAME

Ballard P.C.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA E 27-24N-R5W

12. COUNTY OR PARISH 13. STATE

Rio Arriba

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9/25-28, 1981

1. Pull 1" tubing and run 1 1/4" tubing in hole, circulate.
2. Spot 43 sx cement plug in open hole to top of liner (2100'-2302')
3. Perforate 2 squeeze holes at bottom of Ojo Alamo (1890')
4. Spot a 31 sx cement plug across perforations. Displace 20 sx thru perforations (1890'-1790').
5. Perforate 2 squeeze holes at 200' and circulate 85 sx cement plug to surface leaving casing full.
6. Install a P & A marker.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Brandon* TITLE *Production Engineer* DATE *10-21-81*

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

"Complied with general requirements. Site ready for inspection."

*nmccp*  
FARMINGTON COPY