



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 078861  
Unit \_\_\_\_\_

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 17, 1960

Kinchote-Federal  
Well No. 1 is located 990 ft. from N line and 990 ft. from E line of sec. 21

NE NE 21  
(¼ Sec. and Sec. No.)

24N 9W  
(Twp.) (Range)

NMPM  
(Meridian)

Monte-Gallup  
(Field)

San Juan  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 6805 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate bedding jobs, cementing points, and all other important proposed work)

- Kinchote-Federal No. 1  
PEID 9389', 8-3/8" - 302', 5 1/2" 3404 - 125 ex.  
Perforations 3320-25; 3329-33. Gallup Sand. To plug and salvage 5 1/2".
1. Squeeze w/cement perforations 3320-25 and 3329-33.
  2. Load hole and shoot off pipe above cement.
  3. Place 100' cement plug at point where casing is parted.
  4. As casing is pulled place cement plug through Pictured Cliff Zone 1640-1815'.
  5. Place 100' plug from 252 to 352'.
  6. Plug top of surface pipe w/cement and install marker.
  7. Restore surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Gulf Oil Corporation

Address Production Department

P. O. Box 1346

Salt Lake City, Utah

ORIGINAL SIGNED

By \_\_\_\_\_

Title Area Production Manager