

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

| | |
|--|---|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> | 5. LEASE DESIGNATION AND SERIAL NO. NM-0557389 |
| 2. NAME OF OPERATOR Harry L. Bigbee | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME X |
| 3. ADDRESS OF OPERATOR P.O. Box 669, Santa Fe, New Mexico 87501 | 7. UNIT AGREEMENT NAME X |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990 FSL and 1793 FWL Sec.12 TWP 24N Rge 8W | 8. FARM OR LEASE NAME NANCY |
| 14. PERMIT NO. | 9. WELL NO. 3 |
| 15. ELEVATIONS (Show whether DF, RT, CR, etc.) G.L. 7202 | 10. FIELD AND POOL, OR WILDCAT Wildcat |
| | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 12-24N-8W |
| | 12. COUNTY OR PARISH San Juan |
| | 13. STATE N.M. |

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


Set model N Packer at 6845

Perforate 6804 - 6806)
6808 - 6812) Two holes per foot
6815 - 6831)

Spot 250 gallons 15% MCA

Spearhead 5,000 gals of 28% acid ahead of oil frack using 25,000 lbs of 10-20 sand.

Set model N packer at 6100.



Perforate Gallup at 6060 to 6074 two (2) holes per foot.

Frack with water and 15,000 lbs of 40-60 sand.

Swab water back, drill out plugs and swab. Put well back in operation.

Job to start approx. 9-18-68

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE 9-12-68

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

SEP 13 1968

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.