			1		
Form 9-331 (May 1963)	UNITED STATES	SUBMIT IN TRIPLICATE® (Other instructions on re-	Form approved. Budget Burolu No. 42-R1424.		
	DEPARTMENT OF THE INTERIOR	( verse side)	5. LEASE DESIGNATION	AND SERIAL NO.	
	GEOLOGICAL SURVEY		ST 79101		
	SUNDRY NOTICES AND REPORTS ON	WELLS	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
3	SUNDRY NOTICES AND REPORTS ON				
(Do not use	e this form for proposals to drill or to deepen or plug back Use "APPLICATION FOR PERMIT—" for such propos	-	•		
<del>[.</del>			7. UNIT AGREEMENT N.	/ 71 E	
OIL GA	AS OTHER		East Pisti V	, 2	
2. NAME OF OPERAT			8. FARM OR LEASE NA:		
miro111+ 04	1 Company				
3. ADDRESS OF OPE			9. WELL NO.	<del></del>	
1950 Line	ola Stroot, Senvar, Colorado 80203		99		
1. LOCATION OF WE	FELL (Report location clearly and in accordance with any State requirements.		10. FIELD AND POOL, OR WILDCAR		
See also space 1 At surface	See also space 17 below.)			Bisti Dover Callup	
				11. SEC., T., R., M., OR BLK. AND	
660 TST.	and 660 TEL Section 1-24N-10W	SURVEY OR AREA			
201 4 10 7 2114 5500 2011 2 2 11 2 30			Section 1-247-10/		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT,	GR, etc.)	12. COUNTY OR PARISE	1 13. STATE	
	5060' KD 6057' GR		San Juan	Nor. No. 6	
16.	Check Appropriate Box To Indicate Natu	re of Notice. Report, or C	Other Data	-	
	NOTICE OF INTENTION TO:	SUBSEQU	ENI REFURI UE.		

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

All depths shown are from ground level. 6-15-71 - MI & BU Aztec Well Service Unit pulled rods and tubing. Spotted cenant from 5498 to 5399. Rigged up and worked 5-1/2 casing. Shot off 5-1/2 casing at 1354. Spotted cament from 1994 to 1718, 39134' above 5-1/2" casing stub. Spotted cement from 1128' to 1028'. Spotted 10' plug in surface casing. Installed dry hole marker. Completed 2 & A 6-25-71.



REPAIRING WELL

ALTERING CASING

ABANDON MENT\*

	SIGNED	TITLE Tond Clerk	DATE
(	This space for Federal or State office use)		# · ·
_	APPROVED BY	TITLE	DATE