

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Order: 1. Application for Permit to Drill; 2. Report; 3. Final Report)

Form approved
Budget Bureau No. 42-R1424
5. LEASE DESIGNATION AND SERIAL NO.
NM-087657

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different formation. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME Escrito Gallup	
2. NAME OF OPERATOR BCO, Inc.		8. FARM OR LEASE NAME Escrito Gallup Unit	
3. ADDRESS OF OPERATOR 135 Grant, Santa Fe, New Mexico 87501		9. WELL NO. 3	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 855' FSL 410' FEL Sec 13 T24N R8W NMPM		10. FIELD AND FORM. OF WILDCAT Escrito Gallup	
14. PERMIT NO.		11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA 13-24N-8W NMPM	
15. ELEVATIONS (Show whether DF, RT, CR, etc.) GR 7089 DF 7098		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZING

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and points pertinent to this work.)

We believe the well has a casing failure above the Gallup formation, we intend to set a bridge plug above the present perforations in the Gallup, isolate the hole in the 4-1/2" casing and cement same to fix it. We will subsequently drill out the cement, remove the retrievable bridge plug and place the well back in operation.



FEB 06 1980

U. S. GEOLOGICAL SURVEY
DURANGO, COLO.

18. I hereby certify that the foregoing is true and correct

SIGNED

Harry R. Bigham

TITLE

President

DATE

1/23/80

(This space for Federal or State official use)

APPROVED

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ak Smith

FEB 7 1980

NM002

CARL A. BARRICK

*See Instructions on Reverse Side