3-NMOCC 1-Mes	a (Val Jones)	l-Northwest Pi	peline (Jim Prenti	ce) 1-F	тте
	?				Form C-103
DISTRIBUTION					Supersedes Old C-102 and C-103
SANTA FE	/ NE'	MEXICO OIL CONS	ERVATION COMMISSION		Effective 1-1-65
FILE	7				
	<del>-   -  </del>			5a.	Indicate Type of Lease
U.S.G.S.	<del></del>				State X Fee
LAND OFFICE				5.	State Oil & Gas Lease No.
OPERATOR				ļ ·	LG 1917
					virininini
100 VOT USE TUIS 5001	SUNDRY NOTICES	AND REPORTS ON	WELLS ack to a different reservoir.		
USE "	APPLICATION FOR PERMIT -	" (FORM C-101) FOR SUC	H PROPOSALS.)		
1,		,		7.	Unit Agreement Name
OIL GAS WELL WELL	X OTHER-				
2. Name of Operator					Farm or Lease Name
Dugan Production Corp.					Mesa
3, Address of Operator					Well No.
Por 234	Farmington N	4 87401 ·		1	3
Box 234, Farmington, NM 87401					. Field and Pool, or Wildcat
4. Location of Well  UNIT LETTER 0 790 FEET FROM THE South LINE AND 1750 FEET FROM					Wildcat - PC
UNIT LETTER O	,	FROM THE SOULI	LINE AND TIO	FEET FROM	WITTEN TO THE TOTAL TO THE TANK THE TAN
ı		•	~		
THE East	NE, SECTION16	TOWNSHIP 24N	RANGE	имрм.	
i					
	15. 1	Elevation (Show whether	DF, RT, GR, etc.)	12	. County
		6797	GR		San Juan
16.	Check Annionriate	Box To Indicate N	lature of Notice, Repor	rt or Other	Data
	E OF INTENTION T		<del>-</del>		EPORT OF:
NOTIC	E OF INTENTION I	0.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	LQULIT IX	er out or .
<del></del> 1				<del>[ ]</del>	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK	H	ALTERING CASING
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JQB	• 📙	
			OTHER		Completion X
OTHER				· · · · •	•
			<u> </u>		
17. Describe Proposed or Conwork) SEE RULE 1103.	ipleted Operations (Clear	ly state all pertinent det	ails, and give pertinent dates,	, including est	imated date of starting any proposed
WORK) SEE ROLE 1103.					
10.00.00					
10-22-76	. 3 . 2	on Moll Commis	a guabhing unit	Swahhad 1	Fluid level down to
PBTD 2015'. Mo	ved in Farmingt	on well service	swapping unit.	swapped :	fluid level down to
1200'. Go Inte	rnational ran g	amma-ray corre.	lation log. Perro	rated 10	holes 1893-1895½'.
Swabbed well, n	o fluid entry o	r gas entry. <i>I</i>	Acidized well with	250 gals	s 15% HCl. Break-
down 1600 psi, pumped in @ 250 psi, under-displaced with 10 bbls fluid. ISDP 100 psi.					
Shut well in.					
Didd World In-					
11-9-76					
Western Company frac Pictured Cliffs perfs 1893-1895 using 294 hp, 18,900 lbs 10-20 sand,					
341 bbls wtr with 20 lbs J-2/1000 gals and 3/4 gals FSF/1000 gals. IF 1100 psi, Max 1100					
psi, Min 1000 psi, Avg 1000 psi, Final 1000 psi, ISDP 500 psi, 10-min Shut-in 450 psi,					
		I, FINAL 1000	P31, 1021 300 P31,		ondo di los pou,
Avg IR 12 B/M.	Shut well in.				
11-16-76					
Digged up and r	an 58 its 1-1/4	" OD 2.3# V-55	10R reg tbg. TE	1922.421	set @ 1924' RKB.
Kigged up and i	n hottom Plot	well to atmos	phere 1 hr after 1	anding th	ha. Nippled up
Has Cross pin o	n boccom. brew	aced down Farm	ington Well Servic	e swabbi	ng unit.
wermead and sn	ut werr mi. Kr	gged down raim	ingcon werr bervre		
18. I hereby certify that the j	mormation above is true	and complete to the best	of my knowledge and belief.		
15. Thereby certally and the	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•	-		
$\sim 10^{-10}$	/ILAA.		T7		11-17-76
SIGNED	Dugan	TITLE	Engineer		DATE TI-1/-/6
Thomas A.	AVR. Kendrick				at a creation
Original Signed by	"[]	·			
	•	i title	residence and a second control of the second control of the second control of the second control of the second		DATE
APPROVED BY	LE ANY	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
CONDITIONS OF APPROVAL	L, IF ANTI			N U	(2) 3 /