	ruer r-Nordiwest ripe		/
(Mickel & Z	Subatch) (Randolph) UNITED STATES	SUBMIT IN TRIPLICATE*	Form approved.
(Mg.) 10897~			Budget Buréau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
DEPARTMENT OF THE INTERIOR verse side)			
GEOLOGICAL SURVEY			NM 16589/
CHAIDO	NOTICEC AND DEDODE	C ON WELLS	6. IF INDIAN, ALVOTTEE OR TRIBE NAME
SUNDRY	NOTICES AND REPORT	ON WELLS	
(Do not use this form f Use "	or proposals to drill or to deepen or pl 'APPLICATION FOR PERMIT—" for su	ch proposals.)	
1.			7. UNIT AGREEMENT NAME
OIL GAS X			
	OTHER		8. FARM OR LEASE NAME
2. NAME OF OPERATOR		i	SER B TFET
Dugan Produc	ction Corp.		Mountain
Box 234, Farmington, NM 8740]. 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1050' FSL - 850' FWL			9. WELL NOT BE TO THE REPORT OF THE PROPERTY O
			[변화물 유 3 회 제 변호] 제
			10. FIELD AND POOL, OR WILDCAT
			Undesignated - PC
			11. SEC., T., B., M., OR BLK. AND -
			SURVEY OR AREA
			Sec 15, T24N, R8W = 12, COUNTY OR PARISH 13, STATE
14. PERMIT NO.	15. ELEVATIONS (Show wheth	er DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	686	O' GR	San Juan NM
16. CI	L. I. A Pau Ta Indian	te Nature of Notice, Report, or O	the Data
	seck Appropriate box to indicat	re ladiure of labrice, Report, or O	ther Data and the state of the
NOTICE	OF INTENTION TO:	SUBSEQU	ENT REPORT OF
	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
TEST WATER SHUT-OFF	- ·		ALTERING CASING
FRACTUBE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	17 J 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* Completion x
REPAIR WELL	CHANGE PLANS	(Other)	of multiple completion on Well
(Other)	L	Completion or Recomple	etion Report and Log form.)
	SEE ATTA JAN 4 1 OIL CON. DIST.	977 u. s. c. c. c. c. c. c.	The a might be designed by the application of the problem of the animal problem of the a
	A. Dugan TITLE	Engineer	DATE12-30-76
(This space for Federal or	State office use)		
IDDD ARED BY	· V		DATE
CONDITIONS OF APPRO	VAL. IF ANY:		PAN .
			그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그 그

DUGAN PRODUCTION CORP.

MOUNTAIN #3

REPORT OF COMPLETION

10-6-76

Moved in and rigged up Farmington Well Service swabbing unit. Go International attempted to run correlation log, stopped @ 1154', put on one 35# sinker bar above logging tool, went to PBTD of 2081'. Ran gamma-ray correlation log. Swabbed csg down to 1550'. Perforated w/one 2-1/8" glass jet/ft 2042-2047' (5 holes). Swabbed well down, no indication of gas or fluid entry. Perforated w/one 2-1/8" glass jet/ft 1985-1991' (6 holes). Swabbed well, no indication of gas or fluid entry. Released swabbing unit.

11-19-76

Moved in and rigged up Farmington Well Service swabbing unit. Go International perforated 19852-1988 with 4 holes/ft (10 holes) 2-1/8" glass jet. Swabbed well down, very slight show of gas and small amount of water, very salty.

11-20-76

Acidized all perfs w/250 gal 15% HCl acid. Breakdown press 1500 psi. Dropped 15 rubber balls in 2 stages, no press increase. Followed acid w/20 bbls wtr. Treated fluid with 1-1/4 gal liquid soap. Swabbed well back after being shut in approx 3 hrs, slight show of gas.

12-22-76

Moved in and rigged up Farmington Well Service swabbing unit. Ran 59 jts 1-1/4" OD 2.3# J-55 10R NEUE tbg. TE 1983.22' set @ 1982' RKB w/Baker Model "C" packer @ 1982' RKB between perfs (19852-1988') and (1985-1991'). Swabbed well 2-1/2 hrs. Csg press up to 200 psi. Shut well in for night.

