

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations.
See also space 17 below.)
At surface

970' FSL - 1740' FEL

RECEIVED

JUN 09 1986

14. PERMIT NO.

15. ELEVATIONS (Show whether on BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
6709' GL

5. LEASE DESIGNATION AND SERIAL NO.

NM 2337

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Chaco

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Potwin P.C.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T 24N, R 8W, NMPM

12. COUNTY OR PARISH 13. STATE

San Juan

NM

18.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

We plan to plug and abandon the subject well as follows:

1. Fill 2-7/8" OD, 6.4#, J-55, 10R, NEUE tubing for casing from P.B.T.D. of 1932' to surface with 53 sx class "B" neat cement.
2. Install permanent dry hole monument.
3. Fill all pits.
4. Clean well location of all equipment, pipe, junk and trash.
5. Accomplish surface restoration as specified.
6. Cut off tie-downs.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan

TITLE Geologist

DATE 6-6-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

JUN 10 1986

DATE

AREA MANAGER
FARMINGTON RESOURCE AREA