4-USGS (Farmington) 1-Tenneco (venus) i-rile		
Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE I	S SUBMIT IN TRIPLIC (Other instructions o	Form approved. Budget Bureau No. 42 5. LEASE DESIGNATION AND SERI.	
	GEOLOGICAL SUR		NM 5991	्रं स राज्य
			6. IF INDIAN, ALLOTTEE OR TRIB	E NAME
SUN	IDRY NOTICES AND REPO	ORTS ON WELLS		. <u> </u>
(Do not use thi	form for proposals to drill or to deepen Use "APPLICATION FOR PERMIT_"	or plug back to a different reservoir.		. == .5 ≥,
	Use "APPLICATION FOR FERMIT"	for such proposition,	7. UNIT AGREEMENT NAME	33
OIL GAS				1
WELL WELL	X OTHER			
2. NAME OF OPERATOR			8. FARM OR LEASE NAME.	i Januara Tantana
Dugan Pr	oduction Corp.		June Joy	<u> </u>
3. ADDRESS OF OPERATO	B		9. WELL NO.	,
Box 234,	Farmington, NM 87401		#1 **	
4. LOCATION OF WELL	Report location clearly and in accordance	with any State requirements.*	10. FIELD AND POOL, OF WILDCA	.T. 5 . 5
See also space 17 be At surface	low.)		Wildcat Sign	<u></u> ;
790	FNL - 1850' FWL		11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA	, ä ä
• • •				
•			Sec 25 T24N R10W	, F 3
14. PERMIT NO.	15 ELEVATIONS (Show	whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STA	
14. PERMIT SO.		50' GR		NM-
16.	Check Appropriate Box To In	dicate Nature of Notice, Report), or Other Data ()	ξ <u>.</u> ξ.
	NOTICE OF INTENTION TO:		TING MANUAL DEPONDS ARE	្តទិ
·	MOTICE OF INTENTION TO		THE STATE OF THE S	=1
TEST WATER SHUT	OFF PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WALL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	T ALTERING CASING	-
SHOOT OR ACIDIZE	ABANDON*	X SHOOTING OR ACIDIZIN		
REPAIR WELL	CHANGE PLANS	(Other)	To a selection on Wall	<u> </u>
(Other)		Completion or B	results of multiple completion on Welf- Recompletion Report and Log form.)	
	OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give pertinent	t dates, including estimated date-of star	rting any
proposed work. nent to this work	if well is directionally drilled, give subs	urface locations and measured and true		
	,		To 93 Radio	
TD 1535'				1
TD 1535'	•		of Hity do Hity and do do Hity do Hito do Hito	
	to Clay robunda but to 11 ag	Follows.	B	ాణుత్తి కేష
Plan to p	lug and abandon well as	COLIOWS:	Section 19	183
		get.		
1. Spot	cement plug TD to 1400'.		with the second	
			ellinde ellinde khoga gel en gel) en a cutif jathand	(32
2. Spot	cement plug 900' to 700'	•	throd property of the control of the	
	_		The straints that the straints of the straints	steenqon law and loopeeats
Spot	cement plug 100' to surf	ace.	transport	1 <u>5 5</u>
			o author can colde and parel trends of a colder of the colder of broken and parel bits of the colder	org Zeillfar E-Rodesti i
4. Level	location and install dr	y hole marker.	그 그 그를 즐겁게 되는 연락	
		- X		5 F F F F F F F F F F F F F F F F F F F
			price of the company	* 2 d
Verbal in	structions obtained from	P. T. McGrath 6-4-78.		al o N
, 02.000				8 2 3
		· ·	nisi an	<u> </u>
•		Dr. warran	int procedures and practices, either are show on the no chires and practices, either are show on the no abundance of the north state of the north	futions. Any necessity special instruction described in sundification is destructed for and the fution proposals.
			A STAN THE S	2 E 82
			oppore, on the control of the order to the order to the control of the control of the order to t	K C
			Tollor and the service of the servic	Ri spiel Sing ab
			in the control of the state of	医毒素
18 I harahy samiffy +1	at the foregoing is true and correct			9 <u>2</u> 2
16. I hereby certaly to	· T (found		parm = 6-5=78	1 11
SIGNED	<u> </u>	TILE <u>Geologist</u>	DATE = 0-3-70.	<u> </u>
(DL)	Jim I. Jacobs ederal or (State office use)			
(THE SPECE IOL P.	delar or weath outer aboy			Sund Bud Gent
APPROVED BY		ITLE	DATE OP-	
	APPROVAL, IF ANY:		on H	to to

