Form	3160-5
June	1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Expires: March 31, 1993

5. Lease Designation and Serial No.

	NC	)0C-	14-	20-	358	8
6.	If	Indian.	Allon	ee or	Tribe	Name

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

TOP INTERP

SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well JUN 2	7 1994
Oil Gas Other	8. Well Name and No.
2. Name of Operator  COLEMAN, OLL, AND, CAS, INC.	NAVAJO WOOD
COLEMAN OIL AND GAS INC.	9. API Well No.
3. Address and Telephone No.	#1
P. O. DRAWER 3337, FARMINGTON, NM 87499 (505) 327-03	10. Field and Pools or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	BISTI GALLUP
800/N 890/E	11. County or Parish, State
SEC 6,T24N,R10W	SAN JUAN, N.M.
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF N	NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent	Abandonment	Change of Plans	
Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing	
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off Conversion to Injection	
	Other	Dispose Water	
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log (orm.)	

- 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
- (1) SET CIBP AT 5125' AND SPOT 25 SK CEMENT PLUG ON TOP.
- (2) LOAD HOLE W/FRESH WATER AND PRESSURE TEST.
- (3) PULL OUT OF HOLE TO 4200'. SET 24 SK PLUG (POINT LOOKOUT).
- (4) PULL OUT OF HOLE TO 2410'. SET 13 SK PLUG (CLIFFHOUSE).
- (5) PULL OUT OF HOLE TO 1700'. SET 35 SK PLUG (PICTURED CLIFFS & FRUITLAND).
- (6) PULL OUT HOLE. STAND 900' TUBING. RUN IN HOLE W/WIRELINE. PERFORATE 4 HOLE AT 908'. RUN IN HOLE W/958' OF TUBING. (A) ATTEMPT TO CIRCULATE HOLE. IF SUCESSFUL, PUMP 112 SK PLUG OUTSIDE 4-1/2" CASING AND 26 SK PLUG INSIDE 4-1/2" CASING. (0JO ALAMO) (B) IF CIRCULATION CANNOT BE OBTAINED, PUMP 26 SK PLUG INSIDE 4-1/2" CASING. (OJO ALAMO).
- (7) RUN IN HOLE W/WIRELINE AND PERFORATE 4 HOLE AT 274'. (A) CIRCULATE DOWN 4-1/2" CASING AND UP 8-5/8" & 4-1/2" ANNULUS. PUMP SUFFICIENT AMOUNT OF CEMENT TO ESTABLISH GOOD RETURNS, (APPROXIMATELY 85 SKS). (B) IF CIRCULATION CANNOT BE OBTAINED, REPEAT PROCEDURE AT 100' (APPROXIMATELY 35 SKS)
- (8) REMOVE WELLHEAD AND CUT ALL CASING STRINGS BELOW GROUND LEVEL. INSTALL DRYHOLE MARKER.
- (9) CLEAN AND SEED LOCATION ACCORDING TO SPECIFICATIONS.

I hereby gerafy that the foregoing is true and correct Signed The Common Signed	15. 0.	41, 14, 14
	Tille Vice-President	Date June 14, 1994
(This space for Federal or State office use)		
Approved by	Tide	Date
		APPROVED
le 18 U.S.C. Section 1001, makes it a crime for any person know representations as to any matter within its jurisdiction.	wingly and willfully to make to any department or agency of the	e United States any false, fictitious or fraudulent statements

'See instruction on Reverse Side NMOCD