Form 9–331 Dec. 1973

**UNITED STATES** DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY** 

iy nenugh p		Approv	ued.	
			au <b>No. 4</b> 2–1	R1424
5. LEASE			2	
NM_14100	. v	• •	450	
6. IF INDIAN, ALL	OTTEE	OR TE	RIBE NAM	 Е
	- 27	4.5		
7. UNIT AGREEME	ENT N	AME		
<u></u>				
8. FARM OR LEAS	E NAM	IE <		
Mean Betty	Jean	1	, jed	
. 9. WELL NO. 💆	-3 1	;		
1 %	E . E . S	7		
10. FIELD OR WILD	CAT N	AME	= <u>1</u>	
Chacra Wijd	lcat		1 4	
11. SEC., T., R., M.	OR B	LK. AN	ND SURVE	Y OR
AREA 👯	( 3 ); ( 3 ),	<b>(2</b>	-5 # 5 <u>\$</u>	
Sec 14 T24N	R11	W	<u> </u>	
12. COUNTY OR PA	RISH	13. 5	STATE S.	
San_Juan ``	\$ <u>3  </u>		<u>ann</u>	
14. API NO.	- T g	⊇.	- 233	
	= 5	_ 3	설립보통	
15. ELEVATIONS (S	SHOW	DF, K	DB, AND	WD)
6500' GL	!		異なるが	
() \ 35	: Q			
egg. A do d	3 3	<b>3</b> 5.	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
.n 🚺 💆 🖣	<u> </u>	i u t	254F	
(NOTE: Report results	of mul	tiple co	mpletian o	7004
change on Fo	rm 9–3	30.)	3 3 5 5	ZUITE AL
ENTIRE TO SE		Ē	3373	
医多一型 自	J.F	3		
	75	3	<u> </u>	-46
S = 5		+- +		3
all pertinent details,	and	give p	ertinent d	ates.
rectionally drilled, givi	e subs	urface	locations	and
t to this work.)* 기를 일	ر بر رئي	<u> </u>	3 2 3 5	
· · · · · · · · · · · · · · · · · · ·	11. 11.	3	5 5 7 1	
of the second se	= 5	<i>3</i> ∩	でき 計画	
to surface wif	h 48	SX	3335	

## SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a difference reservoir. Use Form 9-331-C for such proposals.) gas XX well other well 2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

P 0 Box 208, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1)

below.) AT SURFACE: 1850' FNL - 790' FEL AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES **ABANDON\*** 

(other)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

17. DESCRIBE PROPOSED OR COMPLETED OPERATTONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine

Plan to plug and abandon as follows:

XX

- Fill 2-7/8" casing from PBTD 1746 cement.
- 2. Install dry hole marker.

Fill pits.

Clean and restore location per BLM instructions.

SUBSEQUENT REPORT OF:

Cut off or remove tie-downs.

1983

N. DIV.

Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I he (eb) certify that the foregoing is true and correct		
Geologist Geologist	DATE	5-23-83
1 J JOJII L. Odcobs		

(This space for Federal or State office use)

DATE

\*See Instructions on Reverse Side

VISTRICT ENGINEER