Form 9-331 6 MMS, Fmn 1 S	So Un Expl	1 File Form Appr	oved. eau No. 47-R1424
Dec. 1973 UNITED STATES		5. LEASE	
DEPARTMENT OF THE INTERIO		M1 24661	
GEOLOGICAL SURVEY		5. IF INDIAN, ALLOTTEE OR	TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different		7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to thin of to deepen or proposals.)		8. FARM OR LEASE NAME July Jubilee	
1. oil gas XX other		9. WELL NO.	
2. NAME OF OPERATOR DUGAN PRODUCTION CORP.	•	2 0. FIELD OR WILDCAT NAME * Unde	
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87401	1	1. SEC., T., R., M., OR BLK.	signated Gallup AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEAR	LY. See space 17	area Sec 29 T24N R9W	. · · · · · · · · · · · · · · · · · · ·
below.) AT SURFACE: 790' FNL - 790' FWL AT TOP PROD. INTERVAL:	1	2. COUNTY OR PARISH 13. San Juan	STATE NM
AT TOTAL DEPTH:		4. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NAT REPORT, OR OTHER DATA	JRE OF NOTICE,	5. ELEVATIONS (SHOW DF,	KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT	REPORT OF:	7028' GL	
TEST WATER SHUT-OFF			·
SHOOT OR ACIDIZE	1002	(NOTE: Report results of multiple	completion or zone
PULL OR ALTER CASING	MR 1 6 1885	change on Form 9-330)	
MULTIPLE COMPLETE		rought on No.	
CHANGE ZONES W. L.			
(other)	Park Commence	-	-
 DESCRIBE PROPOSED OR COMPLETED OPERAT including estimated date of starting any propose measured and true vertical depths for all markers 	n work ii wen is dire:	Library diffied, give sussering	pertinent dates, ace locations and
Plan to plug back Dakota Fo above Dakota perfs (610 dump bailers.	rmation by sett 2-6270') and du	ing a cast iron bri mp 50' cement on br	dge plug at leas t idge plug with a
		(ALLENDA	
		OIL 410 7.9 1982	
		3/19/	
Subsurface Safety Valve: Manu. and Type		Set @ _	Ft.
18 Thereby certify that the foregoing is true and corre	ect	2.5.22	
SIGNED _ / Jim I. Jacobs	Geologist	DATE <u>8-9-82</u>	
(This space	for Federal or State office	use)	ABBBOVED

NMOCC
*See Instructions on Reverse Side

AUG 1 8 198