5 - USGS, Fmn   I McHugh   I- Form 9-331 Dec. 1973	Form Approved.  - Budget Bureau No. 42-R1424
UNITED STATES	5. (14/5)
DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	-BIV E LA COMPANIE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a differen reservoir. Use Form 9–331–C for such proposals.)	t 0. 5494 00 L5405 NAME
	8. FARM OR LEASE NAME Oscar the Grouch
1. oil gas to other	9. WELL NO.
2. NAME OF OPERATOR UGAN PRODUCTION CORP.	10. FIELD OR WILDCAT NAME 등 등중
3. ADDRESS OF OPERATOR	Undesignated Chacra
P O Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA # # # # # # # # # # # # # # # # # # #
below.) AT SURFACE: 790' FNL - 790' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan Tall ANM Tall
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	<b>14. API NO.</b> 축출생활 구 것되고면 문급보다 중 중요되다
<del></del>	
PROUTET FOR APPROVAL TO: SUDCEOUTERT PEPOPT OF	15, PLENATIONS (SHOW DF, KDB, AND WD)  6574 GL  (NOTE: Report lessuits of multiple completion or zone SUR Change on Form 9–330.)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF TEST WATER SHUT-OFF	Vicinia de propies
FRACTURE TREAT	ACROS I SERVICE CROSS
SHOOT OR ACIDIZE  REPAIR WELL  T  SHOOT OR ACIDIZE  T  SCR 1	(NOTE: Report results of multiple completion or zone SURVichange on Form 9–330.)
PULL OR ALTER CASING	SURVEHANGE on Form 9-330.)
MULTIPLE COMPLETE	ogottur.
ABANDON*   \[ \text{\sqrt{1}} \ \text{\sqrt{2}}	
(other)	े पडाउँव हे हेर्ने दे
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly strincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin	directionally drilled, give subsurface locations and
Plan to plug and abandon as follows:	2000 2000 2000 2000 2000 2000 2000 200
1. Fill 2-7/8" O.D., 6.5#, 8 Rd, EUE tu	jagg ្តី ម៉ូក្រី bing for casing from PBTD 1773' to
surface using 49 sx class "B" neat c	ement.
2. Install permanent dry hole monument.	18. 18. 18. 18. 18. 18. 18. 18. 18. 18.
<ul><li>3. Fill all pits.</li><li>4. Clean well location of all equipment</li></ul>	nino junk Porch frack
5. Restore surface per surface management	nt agency guidelines.
6. Remove tie-downs.	
	를 즐겁는 살 말이 되었다. 그 사람들이 되었다. 물 물 물 물 물 보다 하는 것이 없는 물 하셨다.
Subsurface Safety Valve: Manu. and Type	Set @ 5 + 5 + 5 + 5 + 5 + 5 + 5 + 5 + 5 + 5
18. I hereby cogify that the foregoing is true and correct	A set of the set of th
SIGNED Sheeman & Sugar TITLE Agent	DATE 2-16:03 5 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Sherman E. Dugan (This space for Federal or State of	APPRUVED
APPROVED BY TITLE TOTALL CONDITIONS OF APPROVAL, IF ANY:	DATE FEB: 2.2.1983
	THE AMES IS SIME
•	DISTRICT ENGINEER