Form 3160-5 (November 1983) (Formerly 9-331)	DEPARTM	l File NITED STATES ENT OF THE INTER OF LAND MANAGEMEI	/	Expires Augus 5. LEASE DESIGNATION	No. 1004-0135 t 31, 1985	
SUN (Do not use this	DRY NOTIC	ES AND REPORTS		NM 36473 6. IF INDIAN, ALLOTTE	E OR TRIBE NAME	
I. OIL CAS				7. UNIT AGREEMENT N.	AME	
2. NAME OF OPERATOR				8. PARM OR LEASE NA	8. PARM OR LEASE NAME	
Dugan Production Corp. 3. ADDRESS OF OPERATOR				9. WELL NO.		
P 0 Box 208, Farmington, NM 87499				10 PIELD AND POOL	10. FIELD AND POOL, OR WILDCAT	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 790' FNL - 890' FWL				Basin Dakota 11. SDC., T., B., M., OR BLK. AND SURVEY OR ARMA		
		•	LAND MANAGERMAN	Sec. 17, T24	<u>1N. R9W. NM</u> PM	
14. PERMIT NO.		15. ELEVATIONS (Show whether 6750 GL; 676	•	12. COUNTY OF PARISI		
16.	Check App		Nature of Notice, Report, or	Other Data	<u> </u>	
•••				SQUENT REPORT OF:		
TEST WATER SHUT-OF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) Plug	MU AB.	LTIPLE COMPLETE ANDON* ANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report resu Completion or Recor	ALTERING C ABANDONME its of multiple completion appletion Report and Log for	on Well	
	se to plug		Gallup and Dakota fo rmation and produce t			
1. Pull	rods and t	ubing.				
2. Set	cast iron b	ridge plug @ 6289'	RKB (50' above top	Dakota perfs).		
3. Dump	50' cement	on plug with dump	bailer.			
4. Re-ru	un tubing a	nd rods and produc	ce Gallup Formation o	nly. β		
				API	1197- n	
				OHC	57. 3	
18. I hereby certify that	the foregoing is to	rue and correct	Coolesiat	/ -	95 1 4 == =	
SIGNED JIM L	Jacobs		Geologist		COVED	
(This apper for Feder	al or State office			AG	£ 93 1985	
APPROVED BYCONDITIONS OF AP	PROVAL, IF ANI	TITLE		,	LENBACH MANAGER	
			0 0.1	recommendation of the	to the best with a first best and the	

*See Instructions on Reverse Side