

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 000136

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal Unit

9. WELL NO.

3-34

10. FIELD AND POOL, OR WILDCAT

Basin

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34, T-25N, R-6W

BMPM

12. COUNTY OR PARISH

13. STATE

Rio Arriba

N. Mex.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR J. Gregory Kerrion & Associates		8. FARM OR LEASE NAME Federal Unit	
3. ADDRESS OF OPERATOR P. O. Box 507, Farmington, N. M.		9. WELL NO. 3-34	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1850' FWL & 1190' FWL SW/4 Section 34, T-25-N, R-6-W		10. FIELD AND POOL, OR WILDCAT Basin	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6383 G.L. 6397 KB	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE N. Mex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☒	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) ☐		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perforated 6634-62 with 26 - 28 gram jet charges. Perforated 6557-80 with 23 - 28 gram jet charges. Perforated 6518-23 with 14 super dyna-jets. Ran straddle tool and broke perfs 6634-62 from 2450 psi to 1900 psi with 200 gal mud acid. Broke perfs 6557-80 from 3450 psi to 2050 psi with 200 gal mud acid. Broke perfs 6518-23 from 3400 psi to 2400 psi with 100 gal mud acid. Sand-water fracked with 40,000 gal 1% Ca Cl₂ solution with 5# Dowell J-111 per 1000 gal and 60,000# 20-40 mesh sand and 49 rubber ball sealers at 32 BPM and 3000 psi. Shut in pressure 2000 psi. Bled to 1200 psi in 20 minutes.

RECEIVED

NOV 11 1963

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

J. Gregory Kerrion

TITLE

Operator

DATE

11-14-63

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.