			/
NO. OF COPIES RECEIVED			,
DISTRIBUTION	NEW MEXICO OIL C	CONSERVATION COMMISSION	France (2, 104
SANTA FE		FOR ALLOWABLE	Form C-104 Supersedes Old C-104 and C-1
FILE	NEQUEST.	AND	Effective 1-1-65
U.S.G.S.	ALITHODIZATION TO TO	ANSPORT OIL AND NATURAL	CAS
LAND OFFICE	AUTHORIZATION TO TR	ANSPORT OIL AND NATURAL	_ GAS
IRANSPORTER GAS			
OPERATOR			
PRORATION OFFICE			
El Paso Natural G	as Company		
Box 990, Farmingt			
Reason(s) for filing (Check proper be New Well Recompletion Change in Ownership	OX) Change in Transporter of: Oil Dry Go Casinghead Gas Condet		
If change of ownership give name			
and address of previous owner	DIFACE		
DESCRIPTION OF WELL AND	Well No. Pool Na	me, Including Formation	Kind of Lease
Federal	l !	valin Pictured Cliffs	State, <u>Federal</u> or Fee
Location	800 Nowth	1650	West
Offit Letter	rectite The	r eet i to	m The
Line o: Section 32 , T	Cownship 26-N Range	2-W , NMPM, R	io Arriba County
DESIGNATION OF TRANSPOL	RTER OF OIL AND NATURAL GA	ıs.	
Name of Futhorized Transporter of C	or Condensate	Address (Give address to which app	
1.1			proved copy of this form is to be sent)
El Paso Natural G	as Company	Box 990, Farm	ington, New Mexico
El Paso Natural G	as Company Casinghead Gas Or Dry Gas X	Box 990, Farm	ington, New Mexico proved copy of this form is to be sent)
El Paso Natural G	as Company casinghead Gas or Dry Gas X as Company	Box 990, Farm Address (Give address to which app Box 990, Farm	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico
El Paso Natural G	as Company Casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge.	Box 990, Farm Address (Give address to which app Box 990, Farm	ington, New Mexico proved copy of this form is to be sent)
R1 Paso Natural G Name of Authorized Transporter of C E1 Paso Natural G	as Company casinghead Gas or Dry Gas X as Company	Box 990, Farm Address (Give address to which app Box 990, Farm	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico
Rl Paso Natural G Name of Authorized Transporter of C Rl Paso Natural G If well produces oil or liquids, give location of tanks.	as Company Casinghead Gas or Dry Gas X as Company Unit Sec. Twp. Rge. C 32 26N 2W	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected?	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico
Rl Paso Natural G Name of Authorized Transporter of C Rl Paso Natural G If well produces oil or liquids, give location of tanks.	as Company Casinghead Gas or Dry Gas X as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool,	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number:	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When
Rl Paso Natural G Name of Authorized Transporter of C Rl Paso Natural G If well produces oil or liquids, give locat on of tanks. If this production is commingled v COMPLETION DATA	casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool,	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected?	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When
Rl Paso Natural G Name of Authorized Transporter of C Rl Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w	casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool,	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number:	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When
Rl Paso Natural G Name of Authorized Transporter of C Rl Paso Natural G If well produces oil or liquids, give locat on of tanks. If this production is commingled v COMPLETION DATA	Casinghead Gas or Dry Gas As Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool,	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number:	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When
El Paso Natural G Name of Authorized Transporter of C El Paso Natural G If well prefuces oil or liquids, give locat on of tanks. If this profuction is commingled v COMPLETION DATA Designate Type of Complet	cas Company Casinghead Gas or Dry Gas X as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well tion — (X)	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper.	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'
El Paso Natural G Name of Authorized Transporter of C El Paso Natural G If well prefuces oil or liquids, give locat on of tanks. If this profuction is commingled v COMPLETION DATA Designate Type of Complet	cas Company Casinghead Gas or Dry Gas X as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well tion — (X)	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper.	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'
RI Paso Natural G Name of Authorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled v COMPLETION DATA Designate Type of Complet Date Spudied	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod.	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deepen Total Depth	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'
RI Paso Natural G Name of Authorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled v COMPLETION DATA Designate Type of Complet Date Spudied	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod.	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deepen Total Depth	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'
El Paso Natural G Name of Futhorized Transporter of C El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled v COMPLETION DATA Designate Type of Complet Date Spudied	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod.	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deepen Total Depth	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth
El Paso Natural G Name of Futhorized Transporter of C El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled v COMPLETION DATA Designate Type of Complet Date Spudied	Casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper. Total Depth Top Oil/Gas Pay CEMENTING RECORD	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
El Paso Natural G Name of Futhorized Transporter of C El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled v COMPLETION DATA Designate Type of Complet Date Spudied	Casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper. Total Depth Top Oil/Gas Pay CEMENTING RECORD	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper. Total Depth Top Oil/Gas Pay CEMENTING RECORD	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper. Total Depth Top Oil/Gas Pay CEMENTING RECORD	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations	Casinghead Gas or Dry Gas A Bas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? give commingling order number: New Well Workover Deeper. Total Depth Top Oil/Gas Pay CEMENTING RECORD	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled we COMPLETION DATA Designate Type of Complete Date Spudied Pool Perforations HOLE SIZE	Casinghead Gas or Dry Gas A Cas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen. Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the series of the ser	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations HOLE SIZE TEST DATA AND REQUEST 10 OIL WELL	Casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen. Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the or be for full 24 hours)	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
R1 Paso Natural G Name of Futhorized Transporter of C R1 Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool HOLE SIZE TEST DATA AND REQUEST 1	Casinghead Gas or Dry Gas A Cas Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen. Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the series of the ser	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations HOLE SIZE TEST DATA AND REQUEST 10 OIL WELL	Casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen. Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the or be for full 24 hours)	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Perforations HOLE SIZE TEST DATA AND REQUEST 10 OIL WELL	Casinghead Gas or Dry Gas A as Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen. Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the or be for full 24 hours)	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks	Casinghead Gas or Dry Gas As Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? Is gas actually connected? In the Well Workover Deeper. Total Depth Top Oil/Gas Pay DEPTH SET In the recovery of total volume of load of the pth or be for full 24 hours) Producing Method (Flow, pump, gas)	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT pil and must be equal to or exceed top allo
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled w COMPLETION DATA Designate Type of Complet Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks	Casinghead Gas or Dry Gas As Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? Is gas actually connected? In the Well Workover Deeper. Total Depth Top Oil/Gas Pay DEPTH SET In the recovery of total volume of load of the pth or be for full 24 hours) Producing Method (Flow, pump, gas)	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT pil and must be equal to or exceed top allo
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled we COMPLETION DATA Designate Type of Complete Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks Length of Test	Casinghead Gas or Dry Gas As Company Las Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Lion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test) Tubing Pressure	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT Pill and must be equal to or exceed top allowed the state of th
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled we COMPLETION DATA Designate Type of Complete Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks Length of Test	Casinghead Gas or Dry Gas As Company Las Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Lion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test) Tubing Pressure	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT Dil and must be equal to or exceed top allowed in the company of the c
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled well COMPLETION DATA Designate Type of Completed Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	Casinghead Gas or Dry Gas As Company Las Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Lion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test) Tubing Pressure	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT pil and must be equal to or exceed top allowed the state of the state o
RI Paso Natural G Name of Futhorized Transporter of C El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled well COMPLETION DATA Designate Type of Completed Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	Casinghead Gas or Dry Gas As Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test) Tubing Pressure Cil-Bbls.	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? Is gas actually connected? Inew Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the pth or be for full 24 hours) Producing Method (Flow, pump, gas) Casing Pressure Water-Bbls.	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'
RI Paso Natural G Name of Futhorized Transporter of C RI Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled well COMPLETION DATA Designate Type of Completed Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	Casinghead Gas or Dry Gas As Company Las Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, Cil Well Gas Well Lion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test) Tubing Pressure	Box 990, Farm Address (Give address to which app Box 990, Farm !s gas actually connected? !s gas actually connected? New Well Workover Deepen	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT Pill and must be equal to or exceed top allowed by the same of t
RI Paso Natural G Name of Futhorized Transporter of C El Paso Natural G If well produces oil or liquids, give locat on of tanks. If this production is commingled well completed to the specific comp	Casinghead Gas or Dry Gas As Company Sec. Twp. Rge.	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? Is gas actually connected? Inew Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the pth or be for full 24 hours) Producing Method (Flow, pump, gas) Casing Pressure Water-Bbls.	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'v. P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT Pill and must be equal to or exceed top allowed by the same of t
RI Paso Natural G Name of Futhorized Transporter of C El Paso Natural G If well produces oil or liquids, give location of tanks. If this production is commingled well COMPLETION DATA Designate Type of Completed Date Spudied Fool Ferforations HOLE SIZE TEST DATA AND REQUEST OIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	Casinghead Gas or Dry Gas As Company Unit Sec. Twp. Rge. C 32 26N 2W with that from any other lease or pool, tion — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AND CASING & TUBING SIZE FOR ALLOWABLE (Test must be a able for this de Date of Test) Tubing Pressure Cil-Bbls.	Box 990, Farm Address (Give address to which app Box 990, Farm Is gas actually connected? Is gas actually connected? Inew Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET Ster recovery of total volume of load of the pth or be for full 24 hours) Producing Method (Flow, pump, gas) Casing Pressure Water-Bbls.	ington, New Mexico proved copy of this form is to be sent) ington, New Mexico When Plug Back Same Res'v. Diff. Res'

VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

)R'G	I'NAL SIGNED E. S. OBERLY
	(Signature)
	Petroleum Engineer
	August 16, 1965
_	(Date)

APPROVED AUG 18 1965 Original Signed By A. R. KENDRICK TITLPETROLEUM ENGINEER DIST. NO. 3

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

 $\,$ Fill out Sections I, II, III, and VI only for changes of owner, well name or number, or transporter, or other such change of condition.