Form 9-331 (May 1963)

16.

UNITED STATES SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

| 5. | LEASE | DESIGNATION | ON AND | SECTOR | MO. |
|----|-------|-------------|--------|--------|-----|
| | Jica | arilla | Cont | . 11 | 0 |

| GEOLOGICAL | SURVEY |
|------------|--------|
| | |

| SUNDRY N (Do not use this form for Use "AP | OICES AND proposals to drill or to PLICATION FOR PER | o deepen or plug MIT—" for such I | back to a different proposals.) | reservoir. |
|---|--|--------------------------------------|------------------------------------|------------|
| | | | | |

| IF INDIAN, ALLOT | ILD ON IS | |
|------------------|-----------|------|
| Jicarilla | Dulce | N.M. |
| | | |


| USE ATT | | 7. UNIT AGREEMENT NAME | |
|---|--|---|--|
| 1. OIL GAS WELL OTHER 2. NAME OF OPERATOR | | 8. FARM OR LEASE NAME Jicarilla A | |
| Tenneco Oil Compan | у | 9. WELL NO. | |
| 3. ADDRESS OF OPERATOR Pox 1714, Durango, | Colorado | 3 10. FIELD AND POOL, OR WILDCAT GALLU | |
| 4. LOCATION OF WELL (Report locati See also space 17 below.) At surface | and Basin Dakota | | |
| | _ | 11. SEC., T., B., M., OR BLE. AND SURVEY OR AREA | |
| 900' FNL 990' FF | ــان | Sec. 19, T26N, R5W | |
| 14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6599 GR | Rio Arriba N.M. | |

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF:

| NOTI | CD OF I | NTENTION TO: | <u></u> ` | · _ | - |
|---|---------|--|---|-----------------------|---|
| TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL | | PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS | WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results of my Completion or Recompletion | Report and Dog Tormi, | - |
| | | | | | |

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones p nent to this work.)*

Rig up 8-24-65 spud, drill to 470. Set 15 jts 8-5/8" 24# J-55 casing set at 470' w/250 sx cement. Circulated cement to surface. WOC. Drilled out from under surface to TD 7590. Reached TD 9-14-65. Ran 235 jts 5-1/2" 15.5# and 14# J-55 casing set at 7590 cemented w/150 cu. ft. cement 1st stage. Cemented 2nd stage through collar set at 6828 w/171 cu ft cement. Circulated stages. WOC. Released rig 9-17-65, opened upper stage collar at 5527, Cement with 1000 cu ft cement followed w/230 sx cemented. Good circulation of cement WOC. Now waiting on completion rig.



| 18. I hereby certify that the foregoing is true and correct Original Signed SIGNED HAROLD C. NICHOLS H. C. NICHOLS | TITLE Senior Production Clerk | DATE 9-22-65 |
|--|-------------------------------|--------------|
| (This space for Federal or State office use) APPROVED BY | TITLE | DATE |