Form 9-331 b (April 1952)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Age	ncy Jicaril	la
Allottee	Jicarilla	Triba
	Contract	

V MOTICES AND DEDODTS ON WEILS

TO A THE PROPERTY OF THE PARTY.	SUBSPOUENT	REPORT OF WATER SHUT-OFF.	**************************************
TICE OF INTENTION TO DRILL		REPORT OF SHOOTING OR AC	
TICE OF INTENTION TO CHANGE PLANS TICE OF INTENTION TO TEST WATER SHU		REPORT OF ALTERING CASING	
OTICE OF INTENTION TO REDRILL OR REP		REPORT OF REDRILLING OR I	
OTICE OF INTENTION TO SHOOT OR ACIDIZ		REPORT OF ABANDONMENT	
OTICE OF INTENTION TO PULL OR ALTER		ARY WELL HISTORY.	
IOTICE OF INTENTION TO ABANDON WELL			
(INDICATE ABO)	VE BY CHECK MARK NATURE OF REPOR	T, NOTICE, OR OTHER DATA)	
		October 29th	, 19 <u></u> 58
ell No. 15-F is located	1650 ft. from N line a	nd 1146 ft. from \(\bigwedge W \)	
1/4 MW 4 Sec. 15	26N 5V	N.M.P.M.	
(14 Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)	Mexico
. Blanco PC Ext.	(County or Subdivision)	(State o	r Territory)
	DETAILS OF WO	moths of proposed casings; indi	cate mudding jobs, cement
	ctive sands; show sizes, weights, and le ing points, and all other important p	moths of proposed casings; indi	1/2" OD 15.5# t.
8-8-58 TD 3301 1 J-55 casis Temperatus 8-24-58 Pressured in one her	ctive sands; show sizes, weights, and le ing points, and all other important points. Set 86 joint as at 3300' with 1 po survey showed to 1 up on casing to 1 ur.	sngths of proposed casings; indicroposed work) 8 32921 of 5=. 00 sacks cement op of cement a. 0006. No pres	1/2" OD 15.56 t. 2350'. sure decrease
8- 8-58 TD 3301 I J-55 casis Temperatus 8-24-58 Pressured in one her	ctive sands; show sizes, weights, and le ing points, and all other important points. Set 86 joint as at 3300' with 1 po survey showed to 1 up on casing to 1 ur.	sngths of proposed casings; indicroposed work) 8 32921 of 5=. 00 sacks cement op of cement a. 0006. No pres	1/2" OD 15.56 t. 2350'. sure decrease
8- 8-58 TD 3301 I J-55 casis Temperatus 8-24-58 Pressured	ctive sands; show sizes, weights, and le ing points, and all other important points. Set 86 joint as at 3300' with 1 po survey showed to 1 up on casing to 1 ur.	sngths of proposed casings; indicroposed work) 8 32921 of 5=. 00 sacks cement op of cement a. 0006. No pres	1/2" OD 15.56 t. 2350'. sure decrease
8-8-58 TD 3301' I J-55 casis Temperatus 8-24-58 Pressured in one has	citive sands; show sizes, weights, and led ing points, and all other important points. Set 86 joint as at 3300' with 1 points at 3300' w	sngths of proposed casings; indicroposed work) 8 32921 of 5=. 00 sacks cement op of cement a. 0006. No pres	1/2" OD 15.56 t. 2350'. sure decrease