## (SUBMIT IN TRIPLICATE)

## \*\*\*

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency Jicarilla
Allotto Jicarilla Triba
Lease No. Contract 108

## SUNDRY NOTICES AND REPORTS ON WELLS

<del></del>			
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SH	UT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING	OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-G	OFF SUBSEQUENT REPORT OF ALTERING	CASING REC	EIVER
NOTICE OF INTENTION TO REDRILL OR REPAIR	SUBSEQUENT REPORT OF REDRILLIN	G OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONA	MENT	7-10-0
NOTICE OF INTENTION TO PULL OR ALTER CAS	SING SUPPLEMENTARY WELL HISTORY	<u> </u>	(王) 13つ8
NOTICE OF INTENTION TO ABANDON WELL		U.S. GEOLOGI	CAT LUP !
(INDICATE ABOVE E	BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DA	PANNINGTON	WEX!
	Movember 1	<b>8th</b> , 19	58
	50 ft. from N line and 1115 ft. from 26x 5W H.R.P.K	( )	13
(½ Sec, and Sec. No.) ('	Twp.) (Range) (Meridian)		
S. Blanco PC Ext,	Rio Arriba	New Mexico	_
	DETAILS OF WORK		
State names of and expected depths to objective ing		/8° OD 24# J-	-55
State names of and expected depths to objective ing 9-25-58 TD 100' RKI casing at 1 surface.	DETAILS OF WORK e sands; show sizes, weights, and lengths of proposed casing points, and all other important proposed work)  B. Set 3 joints 90' of 8-5, 100' with 70 sacks coment.	/8" OD 24# J- circulated to	55
9-25-58 TD 100' RKI casing at 1 surface.  10-23-58 Pressured in 30 minut	DETAILS OF WORK  e sands; show sizes, weights, and lengths of proposed casing points, and all other important proposed work)  B. Set 5 joints 90' of 8-5, 100' with 70 sacks coment.  Ap on casing to 500%. No pites.	/8" OD 24# J- circulated to	55 ease
9-25-58 TD 100' RKI casing at 1 surface.  10-23-58 Pressured a in 30 minut	DETAILS OF WORK  e sands; show sizes, weights, and lengths of proposed casing points, and all other important proposed work)  B. Set 5 joints 90' of 8-5, 100' with 70 sacks coment.  Ap on casing to 500%. No pites.	/8" OD 24# J- circulated to	55 ease
9-25-58 TD 100' REI casing at surface.  10-23-58 Pressured to in 30 minute.  I understand that this plan of work must recompany BL PASO NATURAL	DETAILS OF WORK  e sands; show sizes, weights, and lengths of proposed casing points, and all other important proposed work)  B. Set 3 joints 90' of 8-5, 100' with 70 sacks coment.  ap on casing to 500%. No pites.	/8" OD 24# J- circulated to	55 ease