

## United States Department of the Interior

BUREAU OF LAND MANAGEMENT Caller Service 4104 Farmington, New Mexico 87499

El Paso Natural Ras Company	AUG	9 <b>198</b> 4
P.O. Box 4289		
Farmington, New Mexico 8149	· 9	
Well No. 14 Ring on	Location <u>SE/4NW/4, Sec</u>	12, T.26N.R. TW.
Lease No. Santa Fe 079160		

Gentlemen:

The attached surface rehabilitation requirements, must be completed for the permanent abandonment of this well location. Please notify this office upon completion of the surface rehabilitation operations.

Sincerely yours,

manager Area Manager

Enclosure

co: well file
Micro graphics 943 B 4
Chrono
SBBSELV 8-8-8-4

OIL CON. DIV.

The following surface restoration work needs to be performed on location before final abandonment can be approved.

1.	Well should be plugged and a regulation marker (with well name and and legal location inscribed) cemented in the well bore. OK
<u>/</u> 2.	All fenced pits must be filled in and the fences removed.
3.	Oil stained soil must be cleaned up and buried or removed to an appropriate landfill.
4.	Remove all production equipment.
_√_5.	Remove all purchaser's equipment meter + record
6.	Remove concrete slab from the location.
<b>√</b> 7.	Remove all deadmen (anchors) from the location.
8.	Remove all abandoned flowlines and or risers from the location.
<u>/</u> 9.	Remove all debris from the location.
10.	The access road needs to be blocked with an earthen berm at the point it joins the main road.
11.	The access road needs to be waterbarred to divert water to the sides of the road.
<u>/</u> 12.	Pad and or access road must be leveled, disced and prepared for seeding.
<u>/</u> 13.	All disturbed areas will be resceded during July 1 and Sept. 15th with BLM revised Seed Mix No
	RECEIVED  AUG 10 1984  OIL CON. DIV.  OIL COST. 3

Operator EPNU Well Name 14 RINCON UNIT Date 7-26-89 NW Sec. 12 T. 26 R. 7 Lease No 5F-079160