

(SUBMIT IN TRIPLICATE)

 UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

 Land Office Santa Fe
 Lease No. 079364
 Unit Rincon

SUNDRY NOTICES AND REPORTS ON RECEIVED

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	☒
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


June 30, 1958

 Well No. 11 is located 1980 ft. from [N] line and 760 ft. from [W] line of sec. 6
SW Sec. 6 26N 6E RPM
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Blanco - Tociito Rio Arriba New Mexico
 (Field) (County or Subdivision) (State or Territory)
The elevation of the derrick floor above sea level is 5558 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 6/17/58 an Otis type "H" 8/64" bottom hole choke was set at 6631. A type "H" collar stop was set at 6604 and a 2" type "H" paraffin scraper rabbit installed. The bottom hole choke was run to reduce freezing and lower the OGR. The paraffin scraper was installed to keep the tubing clean of paraffin during the well's normal flow.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXAS NATIONAL PETROLEUM CO.Address 105-1/2 W. BroadwayFarlington, N. H.

By

D. E. A. Johnson
 Area Manager

Title

