

BMG

BENSON-MONTIN-GREER DRILLING CORP.

September 30, 1998

RECEIVED
OCT - 2 1998
OIL CON. DIV.
DIST. 3

Mr. Charles Perrin
New Mexico Oil Conservation Division
1000 Rio Brazos Road
Aztec, NM 87410

Re: EAST PUERTO CHIQUITO MANCOS UNIT
#27 (H-5), SEC. 5, T-26N, R-1E:
BRADENHEAD TEST

Dear Charles:


Referring to our letter of August 25, the completed report of the bradenhead test does indeed show direct communication between the casing and bradenhead.

Our interpretation of the Gamma Ray Induction log forwarded to you by our letter of August 25 confirms there are no water sands exposed below the surface pipe; and as noted in our August 25 letter, we recommend no remedial work be done on this well.

Yours truly,

BENSON-MONTIN-GREER DRILLING CORP.

By:



Albert R. Greer, President

ARG/tlp

API #

30-039 06700