

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐
2. NAME OF OPERATOR
Tenneco Oil Company
3. ADDRESS OF OPERATOR
Box 3249, Englewood, CO 80155
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1595' FSL, 900' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Workover		

5. LEASE
Jicarilla Contract #110
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Dulce, NM
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicarilla A
9. WELL NO.
7
10. FIELD OR WILDCAT NAME
Basin Dakota
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 17, T26N, R5W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6681' GR.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7/23/82 - MIRUSU. NDWH. NUBOP. Pumped into the well to make sure tbg. was clear. RI and tagged prk. RI one jt. inside the prk, no sand fill. Rig broke down. SD for rig repairs.
7/24/82 - POOH w/tbg. RIH w/190' of 1½" tbg. on the bottom of 2-3/8". Tagged the prk and strung into same. Tagged sand fill @ 7495'. Had 45' sand bridge. RIH with rest of tbg. Cleaned out to PBTD @ 7637'. POOH w/tbg. Laid dn tail pipe. RIH w/2-3/8" tbg. Tagged the prk. Pulled up one jt. and landed S/N on very bottom. NDBOP. NUWH. Kicked well around w/N₂. Left well flowing. RDMOSU. Turned back to EPS.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Dennis Wilson TITLE Production Analyst DATE July 27, 1982

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

AUG 04 1982

BY [Signature] FARM DISTRICT *See Instructions on Reverse Side

NMOCC

