

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals

5. Lease Designation and Serial No.

JICARILLA CONTRACT 110

6. If Indian, Allottee or Tribe Name

JICARILLA DULCE, NM

7. If Unit or CA, Agreement Designation

8. Well Name and No.

JICARILLA A #7

9. API Well No.

3003908097

10. Field and Pool, or Exploratory Area

BASIN DAKOTA

11. County or Parish, State

RIO ARRIBA NM

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

AMOCO PRODUCTION COMPANY

Attention:

WAYNE BRANAM, RM 1220

3. Address and Telephone No.

P.O. Box 800, Denver, Colorado 80201

(303) 830-4912

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1595FSL 900FWL Sec. 17 T 26N R 5W UNIT L

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

- ☐ Abandonment
☐ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

AMOCO PROPOSES TO REPAIR THIS WELL PER THE ATTACHED PROCEDURES.

RECEIVED
JAN 25 1995
OIL CON. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Signed

Wayne Branam

Title

BUSINESS ANALYST

Date

12-28-1994

(This space for Federal or State office use)

Approved by

Don R. Stille

Title

for Chief, Lands and Mineral Resources

Date

JAN 24 1995

Conditions of approval, if any:

attached

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

JICARILLA A 7
SEC 17 - T26N - R5W
RIO ARRIBA COUNTY, NM
REPAIR WELL PROCEDURE

1. TOOH with the 2-3/8" production tbg.
2. TIH with bit and scraper for 4-1/2" csg to approximately 7450'. Tag the packer at 7455'. The packer has an open bore.
3. Wireline set a CIBP at 7430'.
4. Cap the CIBP with 10' of sand/barite mixture. Bring the mixture up to 7420'. The mixture should be 33% barite and 67% 20/40 sand.
5. TIH with muleshoe, SN, and 2-3/8" tbg and land intake at 7380'. Check with Ralph Montoya before running the tbg in the well. Ralph may want to run 2-1/16" tbg rather than the 2-3/8" tbg.
6. Swab the well in and RTP.

HICARILLA A 007 140
 Location - 17L-26N-5W
 SINGLE dk
 Orig. Completion - 9/66
 Last File Update - 1/89 by BCB

