

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals)

5. Lease

NMMN-03554

6. If Indian, Allottee or Tribe Name

7. Unit Agreement Name

1. Oil Well ☐ Gas Well ☐ Other ☐
GAS WELL

8. Well Name and No.

BREECH "C" 323

2. Name of Operator:

Caulkins Oil Company

9. API Well No.

30-039-08161-00-S1

3. Address of Operator:

(505) 632-1544

P.O. Box 340, Bloomfield, NM 87413

10. Field and Pool, Exploratory Area

BASIN DAKOTA

4. Location of Well (Footage, Sec., Twp., Rge.)

890' F/S 1190' F/W, M SEC. 14-26N-6W

11. Country or Parish, State

Rio Arriba Co., New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Inspect Tubing

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

17. Describe Proposed or Completed Operations:

8-6-96 Pulled and inspected 2 3/8" tubing for leaks.

No holes found in tubing.

Scale and mud on outside of tubing at approximately 1230' indicated a casing leak.

T.I.H. with tubing cleaning out with air to PBTD at 7610'.

T.O.H. with tubing.

T.I.H. with tubing and 4 1/2" R-3 packer.

Landed tubing at 7513' with packer set at 6797'.

(Continued on page 2.)

RECEIVED

SEP 13 1996

OIL CON. DIV.
DIST. 3

NOTE: The format is issued in lieu of U.S. BLM Form 3160-5

18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT

SIGNED: Robert L. Verquer
ROBERT L. VERQUER

TITLE: Superintendent DATE: 08/16/96

APPROVED BY: _____ TITLE: _____

ACCEPTED FOR RECORD

CONDITIONS OF APPROVAL, IF ANY

SEP 03 1996

FARMINGTON DISTRICT OFFICE
BY 211

NMOCD

Caulkins Oil Company
BLM Sundry Notice for Breech "C" 323
August 16, 1996
Page 2

After packer was set, casing was tested to confirm leak.

We intend to swab well in through tubing to test rate of flow to determine if it is economical to repair well, or if we should P & A well at this time.

We request approval for a sufficient amount of time to conduct tests on this well to determine future remedial action.

Prior to any future repairs, plans will be submitted by Sundry Notice.