

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65


5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-291-3
7. Unit Agreement Name
8. Farm or Lease Name Southern Petroleum Com
9. Well No. 4
10. Field and Pool, or Wildcat Undesignated Chacra
12. County Rio Arriba

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator El Paso Natural Gas Company 3. Address of Operator P. O. Box 289, Farmington, New Mexico 87401 4. Location of Well UNIT LETTER <u>K</u> <u>1450</u> FEET FROM THE <u>South</u> LINE AND <u>1450</u> FEET FROM THE <u>West</u> LINE, SECTION <u>32</u> TOWNSHIP <u>26N</u> RANGE <u>6W</u> NMPM.	15. Elevation (Show whether DF, RT, GR, etc.) 6732' GL

<p>16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data</p>	
<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <u>Repair Casing leak</u> <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MOL & RU
Pull 3715' of 1 1/4" IJ tubing from well.
Run 2 7/8" x 1 1/4" packer and tubing back in the hole.
Set packer above perforations.
Swab well in, to see if well will still produce.
Rig down.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Production Engineer DATE 8-1-80

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT # 3

AUG 4 1980

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

Well must be repaired or plugged after 90 days