Form 3160-5 (November 1994)

DEPARTMENT OF THE INTERIOR

UNITED STATES **BUREAU OF LAND MANAGEMENT**

FORM APPROVED Budget Bureau No. 1004-0135 Expires July 31, 1996

5. Lease Serial No.

Tract	251	Contract 154
11 06.6	LJI	CONTOUR ACT

SUNDRY NOTICES AND REPOR	Tract 251 Contract 154	
		6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to one abandoned well. Use Farm 3160-3 (AP	Maradala Arasha	
abandoned well. Use reministrations (Art	Jicarilla Apache	
	still all all and aids	7. If Unit or CA/Agreement, Name and/or No.
SUBMIT IN TRIPLICATE - Other instruc	nons on reverse side (VA) SATA HADIYA MA	
	22 U(U 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
Type of Well Oil V Gas	8. Well Name and No.	
Oil X Gas Well Other		Jicarilla Apache 16
2. Name of Operator CO OCT 2000		DHC No. 2787
Marathon 011 Company	3H. Phone No. (include area code)	9. API Well No. 30-039-20529
3a. Address		10. Field and Pool, or Exploratory Area
	1905 7 393-7100	BD / MV / Otero Chacra
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		
UL I, Sec. 34, T-26-N, R-5-W	11. County or Parish, State	
1600' FNL & 900' FWL		
- Contract		
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTICE, REPORT	T, OR OTHER DATA
	TYPE OF ACTION	
TYPE OF SUBMISSION	TIPE OF ACTION	
Acidize	Deepen Production	on (Start/Resume) Water Shut-Off
Notice of them		tion Well Integrity
Alter C	asing Fracture Treat Reclama	
X Subsequent Report Casing 1	Repair New Construction Recomp	lete A Other
Change	Plans Plug and Abandon Tempora	arily Abandon RC Otero Chacra
Final Abandonment Notice	D Water D	
Describe Proposed or Coommpleted Operation (clearly state all pert	to injection	did blio
If the proposal is to deepen directionally or recomplete horizontally Attach the Bond under which the work will be performed or provided following completion of the involved operations. If the operation is testing has been completed. Final Abandonment Notices shall be determined that the final site is ready for final inspection.) 7/12 RU pulling unit. ND wellhed. NU BOP. 7/14 TIH w/CIBP, set at 5140'. Add perfs 4635'. Acidize w/1000 gals 15% acid. 7/16 RIH, tag sand at 4993'. Rel pkr. POC 7/17 Clean out to 5140' CIBP. Swab. Swab 7/27 Place well on plunger lift. Drop burn 8/2 POOH w/tbg. RIH w/composite bridge pholes. RIH w/pkr. set at 3752'. Acid containing 59,200# sand. Open well/18/8 RIH, tag sand at 3868'. Rel pkr. POC RIH, tag sand at 5112'. Clean out to 7385', POOH. RIH w/2 3/8" tbg. 8/11 Run after frac log. ND BOP. NU well	POOH w/tbg. Work through tight sport of Mesa Verde from 4725-5045". 18 Frac w/3767 gals Delta 200 w/50, Wh. RIH tag fill at 4973". and flow test. Sper spring and plunger. Swab/test blug, set at 4000". POOH. Perf Chabitze w/1000 gals 10% acid. Frac w/flow test. OH. RIH, clean out to 4000". DO plus of CIBP at 5140". DO CIBP. Chase to	pot about 16' deep. holes. RIH w/pkr, set at 000# sand. Flow back well. cra 3847-3872' w/2 SPF, 50 12,446 gals 70Q N2 foam
SN at 7255° BTM of tbg 7257°		
bin of the 7237		
14. I hereby certify that the foregoing is true and correct	Title	
Name (Printed/Typed) Kelly Cook	Records Process	sor
//	Date 9/22/00	
Bully Cook		
THIS SPACE	FOR FEDERAL OR STATE OFFICE USE	
Approved by /s/ Brian W. Davis	Lands and Mineral Resou	urces Date OCT 0 6 2006
Approval of this notice	does not warrant of Office	
Conditions of approval, if any, are attached. Approval the first that the applicant holds legal or equitable title to those rights which would entitle the applicant to conduct operations thereon.	in the subject lease	