### 8. Ancillary Facilities

No separate drill campsites are proposed

### 9. Wellsite Layout

The drilling site location will be graded and will approximate  $200 \times 250$  with natural drainage to the southeast. Care will be taken while grading to control erosion. A 9' cut will be required on the north side of the wellsite. See attached drillsite layout (Exhibit 3).

# 10. Plans for Restoration of Surface

- A. Following drilling and completion operations, all equipment and material not needed for operations will be removed. Pits containing fluid will be fenced until filled with any additional pits filled and the location cleaned of all trash and junk.
- B. After abandonment, any special rehabilitation and/or revegetation requirements (reseed with seed mixture No. 2) will be complied with and accomplished as expeditiously as possible. All pits should be filled and leveled within 90 days after abandonment.

#### 11. Other Information

The location is in sort of a cove, being bordered on two sides by sandrock cliffs. The sandy clay soil and sandrock has sagebrush, scrub cedar and gramma vegetation with the land used for grazing. There are no residences or structures nearby. The surface is owned by the Indians.

## 12. Operator's Representative

Consolidated Oil & Gas, Inc. Floyd E. Ellison, Jr. Area Production Manager 1860 Lincoln Street Denver, Colorado 80295 Phone (303) 255-1751