Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLICATE® Other Instructions on re- DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Contract #151
(Do not	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.		7. UNIT AGREEMENT NAME
OIL	GAS WELL OTHER	
2. NAME OF OPERATOR		8. FARM OR LEASE NAME Arizona Jicarilla "B"
Southl	and Royalty Company	Arizona Jicarilla "B"
3. ADDRESS OF		
P. O.	Drawer 570, Farmington, NM 87401	#8
4. LOCATION OF See also space At surface	well (Report location clearly and in accordance with any State requirements.* 2 17 below.)	10. FIELD AND FOOL OF WILDCAT SO. Blanco Pictured Cliffs Blanco Mesa Verde 11. BEC., T., R., M., OR BLK. AND
		SURVEY OR ARBA
1075' FNL & 1770' FWL		Sec. 9, T26N, R5W
	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 18. STATE
14. PERMIT NO.	6918 GR	Rio Arriba New Mexico
TEST WATER FRACTURE T SHOOT OR A REPAIR WEL (Other) 17. DESCRIBE PR proposed nent to thi	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS COPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, work. If well is directionally drilled, give subsurface locations and measured and true vertice is work.)* Landed 171 joints of 2 3/8", CSR-55 tubing at 5486. PBR at 3719.	Tubing Report of multiple completion on Well etion Report and Log form.)
	Landed 121 joints of 1 1/2", IJ tubing at 3565'. SIFT.	