

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Contract 103	
2. NAME OF OPERATOR Union Texas Petroleum		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache	
3. ADDRESS OF OPERATOR 375 U.S. Highway 64, Farmington, New Mexico 87401		7. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1450' FNL & 790' FWL		8. FARM OR LEASE NAME JICARILLA H	
14. PERMIT NO.		9. WELL NO. 11	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6781' G.L.		10. FIELD AND POOL, OR WILDCAT Blanco MV/Basin Dakota	
		11. SEC., T., R., M., OR BLE. AND SURVEY OR ARMA Section 18-T26N-R4W	
		12. COUNTY OR PARISH Rio Arriba	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input checked="" type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>
(Other) <input type="checkbox"/>	Commingle <input checked="" type="checkbox"/>	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Union Texas Petroleum desires to restimulate the Dakota and commingle with the Mesaverde pursuant to Order R-7508 and DHC-585. The work will be done as follows:

1. MIRUCT
2. Trip out with both strings of tubing.
3. Cut out packer at 7650'.
4. Acidize Dakota perforations at 7676'-7822' with 1500 gals 15% HCl and 40 7/8" ball sealers. Frac with 130,000# 20/40 sand in 96,000 gals 40# x-linked gel water.
5. Clean up.
6. Run 2-1/16" tubing to 7700'. Resume production.
7. RDMOCT

NMOCB approval is required prior to
start of commingling

RECEIVED
JUL 22 1987
OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert C. Frank

TITLE

Permit Coordinator

DATE

07/10/1987

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

*See Instructions on Reverse Side