

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED
BLM

Sundry Notices and Reports on Wells

99 APR 15 AM 10:23

REC'D ALBUQUERQUE, N.M.

1. Type of Well
GAS

Lease Number
Jic Contract 151
If Indian, All. or
Tribe Name
Jicarilla Apache
Unit Agreement Name

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

RECEIVED
APR 29 1999

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

OIL CON. DIV.
DIST. 3

Well Name & Number
Arizona Jicarilla B #9
API Well No.
30-039-22019
10. Field and Pool
So. Blanco Pict. Cliffs
11. County and State
Rio Arriba Co, NM

4. Location of Well, Footage, Sec., T, R, M
1660' FNL, 800' FWL, Sec. 10, T-26-N, R-5-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other -	

13. Describe Proposed or Completed Operations

3-16-99 MIRU. ND WH. NU BOP. TIH w/2 7/8" gauge ring to 3570'. TOOH. TIH w/2 7/8" CIBP, set @ 3527'. TOOH. TIH, load hole & circ hole clean w/20 bbl wtr. PT csg to 500 psi, failed. SDON. (Erwin Elote, Jicarilla Tribe on location).
3-17-99 Plug #1: pump 16 sx Class "B" neat cmt inside csg @ 2947-3527'. TOOH. Circ hole clean. WOC. SDON.
3-18-99 TIH, tag TOC @ 2947'. TOOH to 2940'. Establish circ. Plug #2: pump 12 sx Class "B" neat cmt @ 2503-2947'. TOOH. Circ hole clean. PT csg to 500 psi, OK. TIH, tag TOC @ 2500'. TOOH. Perf 2 sqz holes @ 1655'. TOOH. TIH w/cmt retainer, set @ 1593'. TOOH. TIH, PT csg to 500 psi/5 min, OK. Establish injection. Plug #3: pump 37 sx Class "B" neat cmt below cmt retainer outside csg. Pump 3 sx Class "B" neat cmt inside csg above cmt retainer to 1553'. TOOH. TIH, perf 2 sqz holes @ 194'. TOOH. Establish circ down 2 7/8" csg & out bradenhead w/10 bbl wtr. Plug #4: pump 85 sx Class "B" neat cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Install dry hole marker w/15 sx Class "B" neat cmt. WOC. RD. Rig released. (T. Muniz, Jicarilla Tribe on location). Well plugged and abandoned
3-18-99.

14. I hereby certify that the foregoing is true and correct.

Signed _____ Title Regulatory Administrator Date 4/12/99

(This space for Federal or State Office use and Mineral Resources)

APPROVED BY [Signature] Title _____ Date 28 APR 1999

CONDITION OF APPROVAL, if any:

Surface restoration COAs in attached ltr. Original sent w/ NOI.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.