Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

J.	Least Schai No.
	NMSF - 080658

SUNDRY	NMSF - 080658  6. If Indian, Allottee or Tribe Name						
SUNDRY Do not use thi abandoned we							
SUBMIT IN TRI	PLICATE - Other instruction	ons on revers	se side. 🛝	<b>0</b>	7. If Unit or CA/Ag	reement, Name and/or No.	
Type of Well     Oil Well		V.	3	₩ - <del>``</del>	8. Well Name and No. REAMES COM 1E		
2. Name of Operator	Contact: Cl	HERRY HLAY		~ ~ × × × × × × × × × × × × × × × × × ×	9. API Well No.		
BP AMERICA PRODUCTION  3a. Address		Mail: hlavaci@l		( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	30-039-22328		
P.O. BOX 3092 HOUSTON, TX 77253	ļ F	Ph: 281.366.4 x: 281.366.0					
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)				11. County or Parish, and State		
Sec 25 T26N R6W NESE 175		SAN JUAN COUNTY, NM					
12. CHECK APPI	ROPRIATE BOX(ES) TO I	NDICATE N	ATURE OF	NOTICE, RI	EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION			ТҮРЕ С	F ACTION			
Notice of Intent	Acidize D		1	☐ Product	ion (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Fractur	e Treat	☐ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New C	onstruction	☐ Recomp	olete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans		d Abandon	-	arily Abandon		
13. Describe Proposed or Completed Op	☐ Convert to Injection	☐ Plug B		☐ Water D	•		
testing has been completed. Final Al determined that the site is ready for f On 6/27/01 Amoco Productior the subject well into the Blanc initiated. Please rescind this p	inal inspection.)  n Company requested permi no Mesaverde, Permission w	ission to aban	don the Basi	n Dakota and	-	d, and the operator has	
We respectfully request to T&	A the wellbore and hold for	possible future	e Mesaverde	recompletion	n.	1 5 y. " " " " " " " " " " " " " " " " " "	
For technical questions please	e call Allen Kutch @281-366	6-7955		RULE_ BY	202 6-01-200	3	
	THIS APPE	ROVAL E	KPIRES_	FEB 1	5 2003		
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #10 For BP AMERICA PRO	308 verified by	the BLM We	Il Information to the Farmin	System gton		
Namc (Printed/Typed) CHERRY	HLAVA Cherry H/a	itle AUTH	ORIZED REF	PRESENTATIVE			
Signature (Electronic S	/ Submission)	D	ate 02/07/2	2002			
<del></del>	THIS SPACE FOR	FEDERAL	OR STATE	OFFICE U	SE		
						2/2:/02	
Approved By	. <del></del>		Title		Date	-/-/02	
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to condu	uitable title to those rights in the su	t warrant or ibject lease	Office				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a cristatements or representations as to	me for any perso any matter withi	n knowingly an n its jurisdictior	d willfully to ma	ake to any department	or agency of the United	

\*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\* ORIGINAL \*\*

CP TO CHERRY 2-26-2002

NMOCO

## San Juan Basin Well Work Procedure

Well Name: Version: Date:	Reames Com 1E #1 2/6/2002				
Budget: Repair Type:	DRA <b>Temporary Abando</b>	nmant			
Objectives:	Temporary Abando	ment		· · · · · · · · · · · · · · · · · · ·	
objectives.					
1. TXA well	bore; hold for future Mesaverd	e recor	npletion.		
Pertinent Info	ermation:				
Location:	Sec 6 T25N R6W			Horizon:	Basin Dakota
County:	Rio Arriba			API#:	30-039-22328
State:	New Mexico			Engr:	Allen Kutch
Lease:				Phone:	(281)366-7955
<del></del>	· · · · · · · · · · · · · · · · · · ·		<del></del>		
Formation To	ps: (Estimated formation tops	)			
Nacimento:		,	Menefee:		
Ojo Alamo:			Point Lookout:		
Kirtland Shale	:		Mancos Shale:		
Fruitland:			Gallup:	6228	
Pictured Cliffs	2932		Graneros:		
Lewis Shale:			Dakota:	7164	
Chacra:	4500		Morrison:		
Cliff House:	4596				
Bradenhead	Test Information:				
Test Date:	Tubing:		Casing:	BH:	
Time BH	CSG	INT	CSG		
5 min					
10 min					
15 min					
Comments:					

## Temporary abandonment procedure Reames Com 1E

- 1. Contact Federal and State agencies prior to starting work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM Brian Davis 505-761-8756).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. ND wellhead. NU BOP's.
- 6. POOH with 2-3/8" tbg, visually inspecting.
- 7. TIH with CIBP on tbg. Set CIBP at 7100' to abandon the DK perfs.
- 8. Spot 12 sack cmt plug 6950' 7100' to isolate the DK.
- 9. Spot 12 sack cmt plug 6128' 6278' to isolate the GP.

the state of the s

10. Load well with inhibited lease water. Test casing to 550 psi for 30 minutes.

The second secon

11. Land 2-3/8" tbg. ND BOP, NU WH. RDMO SU.

Reames Com 1E - Proposed T&A Configuration Rio Arriba County, NM Unit I Section 25 T26N - R6W Run 54

